| Project Ref | Items | 2010/11 Revised £000 | 2011/12 Forecast £000 | 2012/13 Forecast £000 | 2013/14 Forecast £000 | 2014/15 Forecast £000 | 5 Year Total £000 |
|----------------|--|----------------------------|-----------------------------|-----------------------------|-----------------------------|-----------------------------|-------------------------|
| | | | | | | | |
| | Civic Offices, High Street, CM16 4BZ | | | | | | |
| 10/027 | Ceiling replacement GF Conder | | 5.0 | | | | 5.0 |
| 10/028 | Statutory Portable Electrical Testing of electrical appliances | 12.5 | | | | | 26.5 |
| 10/031 | Lift Refurbishment Conder No 3 | 12.0 | | | | | 12.0 |
| 10/032 | Conder Replacement of Failing Lighting Components | 12.2 | | | | | 12.2 |
| 10/033 | Overhaul north and south elevation of Conder eternit roof | 3.4 | | | | | 3.4 |
| 11/023 | Boiler Acid clean & 2 spare modules | | 10.0 | | | | 10.0 |
| 11/024 | Statutory electrical testing of the fixed electrical installations | 4.0 | 46.0 | | | | 50.0 |
| 11/025 | Protection of AC pipework following pigeon infestation | 2.0 | | | | | 2.0 |
| 11/026 | Replacement of fire alarm batteries | 12.0 | | | | | 12.0 |
| 11/027 | Safety revision to mains incoming circuit breaker | 1.0 | | | | | 1.0 |
| 11/028 | Energy Management - AC management and control system | 2.0 | | | | | 2.0 |
| 11/029 | Energy Conservation - 2 No smart electricity meters CS1 & CS2 | 4.0 | | | | | 4.0 |
| 11/030 | Fire Alarm system - replacement of 3No air sampler controllers | 2.0 | | | | | 2.0 |
| 11/031 | Renewal and repair of window blinds | 2.0 | | | | | 2.0 |
| 11/032 | Rectification of original installation defects in lighting cables | | 10.0 | | | | 10.0 |
| 11/033 | Works to the CS1 A/C units to stop the units tripping out. | 5.0 | | | | | 5.0 |
| 11/034 | Overhaul slate roof to old house, replacing defective slates and renewing | | | | | | 3.0 |
| | pointing where defective | 3.0 | | | | | |
| 11/035 | Overhaul slate roof to Homefield House, replacing defective slates & | | | | | | 5.0 |
| | delaminating hip tiles and renewing pointing where defective | 5.0 | | | | | |
| 11/036 | External redecoration of general surfaces and timberworks to Homefield House | | | | | | 2.5 |
| | , and the second | 2.5 | | | | | |
| 11/037 | Jet through all foul and surface drains and carry out remedial works as | | | | | | 4.0 |
| | necessary | 4.0 | | | | | |
| 11/038 | Replacement of worn and damaged floor finishes | 4.0 | | | | | 4.0 |
| 11/039 | External redecoration of general surfaces and timberwork | 2.0 | | | | | 2.0 |
| 11/040 | Preservative treatment to timber fences | 1.2 | | | | | 1.2 |
| 11/041 | Internal redecoration programme | 15.0 | | | | | 15.0 |
| 11/042 | Replacement of numerous co2 fire extinguishers | 2.0 | | | | | 2.0 |
| 12/003 | Replacement lighting components due to age deterioration | 13.0 | | | | | 23.0 |
| 12/004 | Major overhaul fire main pumps | | 4.0 | | | | 4.0 |
| 12/005 | Rectification of original installation deficiencies in lighting cable installations. | | 5.0 | | | | 5.0 |
| 12/006 | Cleaning and renovating Condor building cold water storage tank | | 4.0 | | | | 4.0 |

| 12/007 | External decoration to metal surfaces | | 3.5 | | | | 3.5 |
|--------|--|----------|------|------|-----|------|------|
| 12/008 | Preservative treatment to external timberwork | | 1.2 | | | | 1.2 |
| 12/009 | Internal redecoration programme | | 15.0 | | | | 15.0 |
| 12/010 | Replacement of worn and damaged floor finishes | | 4.0 | | | | 4.0 |
| 13/003 | Replacement of car park barriers | | | 5.0 | | | 5.0 |
| 13/004 | Replacement lighting components due to age deterioration | | | 10.0 | | 10.0 | 20.0 |
| 13/005 | Statutory Testing of Electrical Installation & rectification of defects | | | 4.0 | | | 4.0 |
| 14/002 | Civic control room UPS maintenance and battery replacement. | | | | 2.0 | | 2.0 |
| 14/003 | Rectification of original installation deficiencies in lighting cable installations. | | | | 5.0 | | 5.0 |
| | | | | | | | |
| | Hemnall Street Offices, Epping | | | | | | |
| 11/045 | External redecoration of timber windows, doors and glazed walls | 3.5 | | | | | 3.5 |
| 11/046 | Partial replacement of worn floor coverings to offices and common areas | 3.0 | | | | | 3.0 |
| 11/047 | Internal redecoration of entrance lobby area | 1.5 | | | | | 1.5 |
| 12/011 | Repoint chimney stacks | | 5.0 | | | | 5.0 |
| 12/012 | Internal redecoration programme | | 3.0 | | | | 3.0 |
| | | | | | | | |
| | 63 The Broadway Offices, Loughton | | | | | | |
| 12/013 | Internal redecoration programme | | 3.5 | | | | 3.5 |
| | | | | | | | |
| | Waltham Abbey Town hall Cash Office, Waltham Abbey | | | | | | |
| 11/051 | Partial internal redecoration | 2.5 | | | | | 2.5 |
| | | | | | | | |
| | Brooker Road Industrial Estate, Waltham Abbey | | | | | | |
| 11/054 | Environmental Maintenance Brooker Road Industrial Estate | 2.8 | | | | | 2.8 |
| 12/014 | Environmental maintenance | | 2.8 | | | | 2.8 |
| | | | | | | | |
| | Oakwood Hill Industrial Estate Workshop Units, Loughton | | | | | | |
| 11/057 | Environmental maintenance | 2.4 | | | | | 2.4 |
| 11/058 | Recoat balcony walkway with anti slip finish | 3.0 | | | | | 3.0 |
| 11/059 | Brickwork repointing & metal strapping to balcony support piers and walls | 1.5 | | | | | 1.5 |
| 11/060 | Repairs and waterproofing to asbestos cement roof sheets inc. safe access | 5.0 | | | | | 5.0 |
| 12/056 | External redecoration | | 4.0 | | | | 4.0 |
| 12/057 | Carry out repairs to boundary walls and fences | | 2.0 | | | | 2.0 |
| 12/058 | Clearance of drainage gullies / channels and joint sealing | | 1.2 | | | | 1.2 |
| 12/059 | Environmental maintenance | <u> </u> | 2.4 | | | | 2.4 |
| | | | | | | | |
| | | | | | | | |

| | Langston Road Depot, Loughton | | | |
|------------------|--|-----|------------|-----|
| 11/062 | External redecoration of fire escape stairs | 1.2 | | 1.2 |
| 11/063 | Partial internal redecoration of MOT centre | 2.0 | | 2.0 |
| 11/064 | Depot environmental maintenance | 0.5 | | 0.5 |
| 11/065 | General clearance and cleansing of gutters/cladding | 2.0 | | 2.0 |
| 11/066 | General suspended ceiling repairs | 0.8 | | 0.8 |
| 12/017 | Replacement of worn and damaged floor finishes | i | 2.0 | 2.0 |
| 12/018 | General suspended ceiling repairs | | 0.8 | 0.8 |
| 12/019 | Internal redecoration programme | i | 2.5 | 2.5 |
| 12/020 | Depot environmental maintenance | | 0.5 | 0.5 |
| 12/021 | Clean and change fluorescent tubes to MOT centre | | 1.0 | 1.0 |
| | | | | |
| | Epping Depot, Epping | | | |
| 11/068 | Partial internal redecoration | 2.0 | | 2.0 |
| 11/069 | External redecoration of timber, metalwork and masonry | 2.5 | | 2.5 |
| 11/070 | Remedial repairs and waterproofing works to corrugated asbestos cement roof | 5.0 | | 5.0 |
| | sheets to lower offices | | | |
| 12/015 | Repair roofs to stores / workshops | | 2.5 | 2.5 |
| 12/016 | Renewal of external gates to lower yard | | 2.0 | 2.0 |
| | Townwood Donot | | | |
| 12/022 | Townmead Depot External redecoration to timberwork | | 6.0 | 0.0 |
| | Environmental maintenance | 1.2 | | 6.0 |
| 12/023 12/024 | | 1.2 | 1.2 1.7 | 2.4 |
| 12/024 | Watercourse maintenance (addition to programme) | | 1.7 | 1.7 |
| | Loughton Leisure Centre, Loughton (external & structural) | | | |
| 11/074 | Adjust brise soleil shading system | 0.3 | | 0.3 |
| 11/075 | External redecoration railings to yard / access road | 1.5 | | 1.5 |
| 11/076 | External redecoration of columns, beams and tie bars to front entrance | 1.2 | | 1.2 |
| 11/077 | Drainage jetting | 0.5 | | 0.5 |
| 12/032 | Overhaul roof upstands, flashings, details and fixings | | 4.0 | 4.0 |
| 12/033 | Restore and clean blockwork and reconstituted stone wall in various locations | | 7.0 | 7.0 |
| 12/034 | External decorative preservative treatment to exposed sections of glulam | | 6.2 | 6.2 |
| 12/035 | External preservative treatment to plant room doors, fitness studio guardrails | | 2.8 | 2.8 |
| 12/036 | Drainage jetting | | 0.5 | 0.5 |
| | | | | |

| | Waltham Abbey Swimming Pool, Waltham Abbey (external & structural) | | | |
|--------|---|-----|-----|-----|
| 11/079 | Overhaul roof upstands, flashings, details and fixings | 3.0 | | 3.0 |
| 11/080 | External redecoration of entrance wall | 0.5 | | 0.5 |
| 11/081 | Drainage jetting | 0.5 | | 0.5 |
| 12/043 | Overhaul roof upstands, flashings, details and fixings | | 3.0 | 3.0 |
| 12/044 | External redecoration of entrance wall | | 0.5 | 0.5 |
| 12/045 | Drainage jetting | | 0.5 | 0.5 |
| | Epping Sports Centre, Epping (external & structural) | | | |
| 11/084 | Prepare gym flat roof area and apply Decothane waterproof membrane | 4.5 | | 4.5 |
| 11/085 | Drainage jetting | 0.5 | | 0.5 |
| 11/086 | Remedial repairs and waterproofing works to sports hall roof lights | 3.5 | | 3.5 |
| 12/026 | Overhaul roof upstands, flashings, details and fixings | | 2.0 | 2.0 |
| 12/027 | Prepare squash courts flat roof area and apply waterproof membrane | | 7.5 | 7.5 |
| 12/028 | Renew corroded and fractured downpipes to north side of squash courts | | 0.5 | 0.5 |
| 12/029 | Reseal downpipe connections and plinth coating works at low level (Nichol Road side of sports hall) | | 1.0 | 1.0 |
| 12/030 | Renew mastic seals to movement joints of sports hall walls | | 1.2 | 1.2 |
| 12/031 | Drainage jetting | | 0.5 | 0.5 |
| | Ongar Leisure Centre, Ongar (external & structural) | | | |
| 11/088 | Service and clean car park street lighting including lamp replacement | 2.9 | | 2.9 |
| 11/089 | Drainage jetting | 0.5 | | 0.5 |
| 11/090 | Repointing of isolated areas of external walls | 4.0 | | 4.0 |
| 12/037 | Carry out isolated repairs to flat roof coverings, including to gutters | | 1.5 | 1.5 |
| 12/038 | Replace split / decayed timberwork in various locations | | 2.0 | 2.0 |
| 12/039 | External redecoration to timberwork | | 4.0 | 4.0 |
| 12/040 | Isolated lamp replacements to car park street lighting | | 0.9 | 0.9 |
| 12/041 | Drainage jetting | | 0.5 | 0.5 |
| | Nursery, Pyrles Lane, Loughton | | | |
| 11/092 | Renew defective cold frames and repair brickwork support walls | 1.0 | | 1.0 |
| 11/093 | External redecoration and repairs to outbuildings | 2.5 | | 2.5 |
| 11/094 | internal refurbishment of shower room and staff room | 1.2 | | 1.2 |
| 12/053 | Repair and resurfacing of entrance drive and pathways | | 2.0 | 2.0 |

| 12/054 | Lining works to water tank | | 1.0 | | 1.0 |
|--------|---|------|-----|--|------|
| 12/055 | Isolated replacement works to water system pipework | | 2.0 | | 2.0 |
| | | | | | |
| | Museum, Waltham Abbey | | | | |
| | Partial replacement of worn floor coverings | 1.5 | | | 1.5 |
| 11/057 | Internal redecoration programme | 3.0 | | | 3.0 |
| 12/046 | External redecoration | | 4.8 | | 4.8 |
| 12/047 | Internal redecoration programme | | 3.0 | | 3.0 |
| | | | | | |
| | North Weald Airfield, North Weald | | | | |
| 11/060 | Partial window replacement to building 240 | 1.8 | | | 1.8 |
| 11/061 | Partial external redecoration to gatehouse | 2.0 | | | 2.0 |
| | Maintenance of fire escape routes to gymnastics centre | 0.3 | | | 0.3 |
| | Resurface car park to gymnastics centre | 14.0 | | | 14.0 |
| 11/064 | Timber preservative treatment and renewal of rainwater goods to Archive Store | 2.2 | | | 2.2 |
| | Steel palisade boundary security fencing repairs | 3.0 | | | 3.0 |
| 11/066 | Basic fire precautions, means of escape and intruder detection works in archive | 3.5 | | | 3.5 |
| | store | | | | |
| | Replacement of worn and damaged floor finish to control tower top floor | 2.0 | | | 2.0 |
| | Internal redecoration works to control tower corridors and staircase | 5.0 | | | 5.0 |
| | Carry out isolated repairs to control tower flat roof coverings | | 3.0 | | 3.0 |
| | External decoration to control tower metal surfaces | | 2.5 | | 2.5 |
| | Internal redecoration programme to gatehouse | | 3.5 | | 3.5 |
| | Maintenance of fire escape routes to gymnastics centre | | 0.3 | | 0.3 |
| 12/052 | Steel palisade boundary security fencing repairs | | 3.0 | | 3.0 |
| | | | | | |
| | Council Owned Shopping Parades | | | | |
| 11/074 | Pressure washing and general maintenance of paved areas and walkways | 1.8 | | | 1.8 |
| 11/075 | Redecoration of common areas and enclosed walkways | 3.0 | | | 3.0 |
| 11/076 | Timber preservative treatment to fences and gates | 2.5 | | | 2.5 |
| | Drainage Jetting | 1.5 | | | 1.5 |
| | Environmental maintenance | 6.5 | | | 6.5 |
| | External redecoration of common areas | | 3.0 | | 3.0 |
| | Pressure washing and general maintenance of paved areas and walkways | | 1.8 | | 1.8 |
| | Drainage Jetting | | 1.5 | | 1.5 |
| 12/063 | Environmental maintenance | | 6.5 | | 6.5 |
| | | | | | |

| | General Improvement Areas | | | | | | |
|---------|---|----------|-------|-------|-------|-------|--------|
| 11/080 | Environmental maintenance | 2.0 | | | | | 2.0 |
| 12/064 | Environmental maintenance | | 2.0 | | | | 2.0 |
| | | | | | | | |
| | Health & Safety Works | | | | | | |
| 11/082 | Public building electrical testing, fire precaution requirements, fire fighting | 7.5 | 7.5 | | | | 15.0 |
| | equipment servicing, asbestos management, water treatment works, | | | | | | |
| 4.4.600 | amendments to statutory regulations | | | | | | |
| 11/083 | Specialist asbestos removal, encapsulation / labelling | 3.5 | | | | | 3.5 |
| | CSB Allocated | | | 118.0 | 118.0 | 118.0 | 354.0 |
| | Contingency Fund | | | 11010 | | | 00 110 |
| 11/085 | Emergency Repairs | 12.0 | 5.0 | | | | 17.0 |
| | | | | | | | |
| 12/065 | Consultant Report for 5 year planned maintenance programme | | 20.0 | | | | 20.0 |
| | Civic Offices Direct- Approved DDFs Essential Works- included above. | -20.0 | -95.0 | | | | -115.0 |
| | | | | | | | |
| | Grand Total | 255 | 199 | 137 | 125 | 128 | 844 |
| | Less Existing Planned Maintenance CSB Budget | 118 | 118 | 118 | 118 | 118 | 590 |
| | | 110 | | 110 | | 110 | |
| | Less Existing Planned Maintenance HRA Budget | <u> </u> | 8 | | | | 8 |
| | Net DDF requirement | 137 | 73 | 19 | 7 | 10 | 246 |
| | Current DDF Approved Budget | 175 | 82 | 19 | 7 | 0 | 283 |
| | Additional DDF requirement | -38 | -9 | 0 | 0 | 10 | -37 |
| | | | | | | | |