Project Ref	Items	Status	Capital Fund GF & HRA (Approved Budget) £000	Revenue Fund £000
	Civic Offices, High Street, CM16 4BZ			
	Electrical/Mechanical			
CP008	Photovoltaic Panel on the Main Building, Condor Building and Rear Extension, including pre work protection.	Preliminary Viability / Design Stage.	20.00	
CP102	Energy Saving Grant	Due to commence on site w/comm. 23.09.13 (Homefield House)	20.40	
CP108	Part DDA Compliance. Part resolution of Security problems. Provision of automatic opening doors. C/F 2011/12	Works orders placed	59.21	
CP111	Replacement of failing lighting fittings in offices in the Conder building, with LED lighting	20% Completed. Actively progressing.	29.00	
CP133	Replacement of lighting in offices in the Civic Building inc 323 House with LED lighting	45% Completed. Actively progressing.	20.00	
CP113	Electrical load management infrastructure	In design & under enquiry. 10%	32.00	
CP125	Fire Alarm – Replacement Smoke and Heat Detection Loop 2	Works due to commence September 2013.	11.00	
CP135	Energy Conservation - Provision of Power Factor Correction to increase the efficiency of electricity use	In design & under enquiry. 10%	11.00	
CP136	Energy Conservation - Provision of Voltage Regulation Equipment to reduce energy consumption and electricity charges; intake revision and provision of Air Circuit Breaker	In design & under enquiry. 10%	11.00	
CP137	Electric, Gas and Main MWS Smart Metering	Design 10%. Installation 2%. Works progressing using a staged approach.	16.00	
CP128	North Toilet Fresh Air supply & Extract air handling units replacement	Planned for commencement in the New Year.	15.00	
CP109	Ceiling replacement to Conder 2nd floor corridor including cable management and new Lighting plus Condor staircase	90% Completed. Awaits Fire Engineering works and snagging.	26.70	
CP134	Upgrade Civic Building sensor points and Trend outstation to unify heating control throughout the Main Building	Currently in design and quotation stage.	10.00	
CP129	Plant Room 6 - Replacement AC compressor unit	Planned for commencement over winter period.	16.00	
CP130	Condor Lift Motor Room - Install AC unit	100% Completed.	5.00	

Appendix 1

DF222	Statutory Portable Electrical Testing of electrical appliances	Budget brought forward from 2012/13.		17.20
		Planned for commencement in the new year.		
DF212	Statutory electrical testing of the fixed electrical installations	Budget brought forward from 2012/13. Work		39.60
		programmed for second half of financial year.		
DF224	Energy Efficiency Work	Budget brought forward from 2012/13. Work		19.50
		programmed for second half of financial year.		
DF209	Emergency Lighting Replacement & Battery Replacements	Work programmed for second half of financial		5.00
		year.		
DF211	Auto change over on main domestic hot water pumps	Work programmed for second half of financial year.		2.00
DF207	Mechanical and electrical upgrade to service area above Council Chamber			3.00
DF213	Replace boiler house door to comply with Gas Safe regulations.	Currently seeking quotations.		2.00
	Main Building (External)			
CP106	Roof Access		5.90	
14/001	Brickwork and hopper repairs to parapet walls including access lorry	Carried forward to 2014/15. Next years		6.21
	boom and operator for safe working at height. Budget brought	programme includes working at height at the		
	forward from 2012/13.	same location.		
14/002	Redecoration of general timber surfaces	Complete		4.00
14/003	Reseal joints to parapet wall coping stones	Carried forward to 2014/15. Next years		6.00
		programme includes working at height at the		
		same location.		
14/004	High level decoration to steelwork - North and South elevations inc	Carried forward to 2014/15. Next years		7.00
	for scaffolding for safe working at height	programme includes working at height at the same location.		
DF210	Reseal / remastic 2nd floor windows, inc for scaffolding for safe	Carried forward to 2014/15. Next years		49.00
	working at height	programme includes working at height at the		
		same location.		
	Main Building (Internal)			
CP127	Widen doors to Housing interview room and Conference Room to facilitate DDA	Currently seeking quotations.	16.00	
14/005	Partial replacement of worn floor finishes to offices, common and public areas	Work programmed for second half of financial year.		1.00
14/006	Partial redecoration of offices, common and public areas	Work programmed for second half of financial year.		9.00

14/007	Redecoration of staircases	Work programmed for second half of financial		3.50
		year.		
14/008	Renew 1st floor carpets	Work programmed for second half of financial		4.00
		year.		
14/009	Redecorate Committee Rooms 1+2	Work programmed for second half of financial		1.50
		year.		
	323 House (External)			
CP131 Replacement of decaying and leaking rainwater goods, degraded felt W in gutters, overall soffits/fasciae. Including for scaffolding/safe access y			12.00	
14/010	for working at height. Redecoration of windows and doors	Work programmed for second half of financial		2.60
14/010	Redecoration of windows and doors			2.60
44/044	Apphalt reaf repairs and flocking on Day reaf to Cauth algorithm of	year.		2.00
14/011	Asphalt roof repairs and flashing on Bay roof to South elevation of Link inc safe working at height	Complete		3.00
	Conder Building & Rear Extension (Internal)			
	Refurbishment of ground floor ladies and first floor gents toilets	Complete	14.00	
	Suspended Ceiling in Condor	Complete	1.00	
14/012	Partial replacement of worn floors	Work programmed for second half of financial year.		4.50
14/013	Partial redecoration of offices - Conder	Work programmed for second half of financial		5.00
		year.		
14/014	Redecoration of rear staircase	Work programmed for second half of financial		1.70
		year.		
14/015	Partial replacement of worn floor finishes to offices and common	Work programmed for second half of financial		4.00
	areas	year.		
14/016	Partial internal redecoration of offices and common areas	Work programmed for second half of financial		3.00
		year.		
	Conder Building & Rear Extension (External)			
	Traffic calming - Speed hump and zebra crossing	Complete	10.00	
CP138	Fire escape staircase remodelled including new handrails to rear internal staircase	Design underway	12.00	
CP132	Replacement of degraded felt in gutters, soffits/fasciae. Clear out	Carried forward to 2014/15. Next years	25.00	
		programme includes working at height at the same location.		
	Pyramid Building			
14/017	External & internal redecoration	50% (external) complete		1.25
			398.21	204.56
			000121	201100

	Hemnall Street Offices, Epping External			
14/018		Work programmed for accord half of financial		0.75
14/018	Drainage jetting	Work programmed for second half of financial year.		0.75
14/019	External redecoration to single storey section of building including timber windows, doors and glazed walls at ground floor level including minor repairs and redecorate metal railings, handrails and bollards	Works underway		7.00
14/020	Overhaul/repair zinc wall cladding	Works underway		1.00
	Internal			
14/021	Partial internal redecoration of offices and common areas	Complete		3.00
14/022	Partial replacement of worn floor finishes to offices and common areas	Complete		2.25
			0.00	14.00
	63 The Broadway Offices, Loughton			
CP139	Replacement of obsolete suspended ceiling and associated light fittings	Work programmed for second half of financial year.	11.00	
14/023	Partial replacement of worn floor finishes to offices and common areas	Work programmed for second half of financial year.		4.25
14/024	Partial internal redecoration of offices and common areas	Work programmed for second half of financial year.		3.50
			11.00	7.75
	Industrial Estates			
	Brooker Road, Waltham Abbey			
14/025	Environmental maintenance	Order placed		2.80
14/026	Patch repair and white line lower end car park	Money diverted to emergency watercourse clearance. See report.		4.75
			0.00	7.55
	Oakwood Hill Industrial Estate Workshop Units, Loughton			
14/027	Environmental maintenance	Order placed		1.50
CP005	Upgrade Industrial Units	Money carried forward to 2014/15. £13,000 retained for feasibility work.	313.00	
			313.00	1.50
	Langston Road Depot, Loughton			

Appendix 1

14/028	Basic standard of repair - Health & Safety requirements	Complete		3.75
14/029	Environmental maintenance	Complete		0.50
14/030	Redecoration/Protection of bollards and RSJs	Complete		0.50
14/031	Redecoration of external doors, including minor repairs	Complete		2.00
14/032	Redecoration of external fire escape stairs and provision of anti slip finish	Complete		2.80
14/033	Partial redecoration of internal common areas	Order placed		5.00
			0.00	14.55
	Epping Depot, Epping			
14/034	Basic standard of repair - Health & Safety requirements	Work programmed for second half of financial year.		6.50
14/035	Renewal of gates to lower yard	Work programmed for second half of financial year.		2.00
			0.00	8.50
	Townmead Depot, Waltham Abbey			
14/036	Basic standard of repair - Health & Safety requirements	Order placed		3.00
14/037	Environmental maintenance	Complete		1.20
14/038	Watercourse maintenance (addition to programme)	Order placed		2.50
			0.00	6.70
	Loughton Leisure Centre, Loughton (external & structural)			
14/039	Overhaul roof up stands, flashings, details and fixings	Work programmed for second half of financial year.		4.00
14/040	Drainage jetting	Work programmed for second half of financial year.		0.75
14/041	Fire damper repairs	Additional works requested by the Leisure Contract Monitoring Board.		7.00
			0.00	11.75
	Waltham Abbey Swimming Pool, Waltham Abbey (external & structural)			
CP011	Repairs to flat roof	Awaiting report on roof condition	10.00	
14/042	Upgrading of footpath from rear fire exits	Order placed		3.00
14/043	Preservative treatment to fences and gates	Complete		2.75
14/044	External redecoration of entrance wall	Complete		0.50
14/045	Drainage jetting	Work programmed for second half of financial		0.75

			10.00	7.00
	Epping Sports Centre, Epping (external & structural)			
CP141	Resurface car park including reline marking	Carried forward at the request of the Leisure Contract Monitoring Board.	13.00	
14/046	Drainage jetting	Work programmed for second half of financial year.		0.75
14/047	Overhaul/repair zinc wall cladding	Works underway		1.75
			13.00	2.50
	Ongar Leisure Centre, Ongar (external & structural)			
14/048	Clear all gullies and jet through surface water drains to yards, car parks and walkways including emptying petrol interceptors and cleaning filters	Work programmed for second half of financial year.		1.75
14/049	Service and clean streetlights and replace lamps	Work programmed for second half of financial year.		1.50
14/050	Apply preservative treatment to windows, doors and cladding	Complete		3.75
			0.00	7.00
	Nursery, Pyrles Lane, Loughton			
14/051	Basic standard of repair - Health & Safety requirements	Anticipated Completion March 2014		3.00
			0.00	3.00
	Limes farm Drop-in Centre/Multi-use Games Area			
14/052	Clear all gullies and jet through surface water drains	Responsibility for this area is now ECC.		0.15
14/053	Clean and change lamps to floodlights including safe access for working at height	Order placed		1.25
			0.00	1.40
	Museum, Waltham Abbey			
14/053	Maintenance of boiler	Anticipated Completion March 2014		0.50
14/054	Partial replacement of worn floor finishes to offices and public areas	Removed from programme due to imminent closure of the Museum.		2.00
14/055	Sand and reseal timber flooring to public areas	Removed from programme due to imminent closure of the Museum.		2.50
14/056	Partial redecoration of offices and public areas	Removed from programme due to imminent closure of the Museum.		3.00

14/057	Improvements to lighting installations and controls (see Museum	Removed from programme due to imminent		2.50	
	Manager)	closure of the Museum.			
			0.00	10.50	
	North Weald Airfield, North Weald				
	Gatehouse (External)				
14/058	External redecoration and timber treatment	Complete		2.25	
	Gatehouse (Internal)				
14/059	Internal redecoration of offices and common areas	Order placed		3.50	
	Overhaul ceiling	Work programmed for second half of financial		1.50	
		year.		-	
00405	Control Tower (External)		c		
	Prepare existing flat roof surfaces and apply waterproof coating	Complete	5.77		
CP140	Upgrade antiquated vertical means of escape ladders to comply with current H&S standards	Work programmed for second half of financial year.	8.00		
14/061	Replace areas of broken glass	Budget brought forward from 2012/13. Complete		6.03	
14/062	External redecoration to concrete, masonry and metalwork including safe access for working at height	Works underway		5.00	
	Gymnastics Centre (structure, external and roof only)				
14/063	Maintenance of fire escape routes including clearance of vegetation	Work programmed for second half of financial year.		0.30	
14/064	Preservative treatment to timber oil storage tank enclosure	Complete		0.60	
	Archive Store (External)				
14/065	Repointing to external walls	Complete		1.00	
	Preservative treatment and redecoration to external timber fasciae, soffits, doors and panels	Complete		2.75	
	Building 240 - Fire Station (External)				
CP144	Overlay existing felted roof, include for safe access for working at height.	Order placed	10.00		
14/067	Internal redecoration of toilet and lobby areas	Complete		0.80	
14/007			23.77	23.73	
_	Chigwell Row Recreation Ground, Chigwell				
CP142	Replacement of failed and damaged concrete path adjacent court area including provision of access route for contractors vehicles	Work programmed for second half of financial vear.	17.00		

CP143		Work programmed for second half of financial	10.00	
	car park, including minor concrete repairs	year.		
			27.00	0.00
	The Limes Centre, Chigwell			
CP145	Install a Building Management System to control the heating and ventilation	On hold until completion of snagging works under the building construction contract	10.00	
			10.00	0.00
	Ongar Public Toilets, Ongar			
14/068	Jet through foul water drainage system	Work programmed for second half of financial year.		0.15
14/069	Prepare and redecorate all timber and metalwork surfaces	Complete		1.50
	Prepare and redecorate ceilings	Complete		1.00
	· · · · · · · · · · · · · · · · · · ·		0.00	2.65
	Council Owned Shopping Parades			
	Borders Lane, Loughton (58 to 76)			
14/071	Partial repoint of brick wall enclosing rear yards including minor repairs as necessary	Order placed		4.00
14/072	Drainage Jetting	Work programmed for second half of financial vear.		0.75
14/073	Environmental maintenance	Order placed		0.80
14/074	External redecoration of extensions and exposed low level timber and metalwork to rear of parade	Order placed		2.50
	Hillhouse, Waltham Abbey (1 to 12)			
CP124	Overlay cracked asphalt roofs covering to rear extensions	Order placed	7.00	
14/075	Clear all gullies and jet through surface water drains to yards, car park and walkways	Work programmed for second half of financial vear.		0.50
	Limes Avenue, Chigwell (548 to 562)			
14/076	Pressure washing and general maintenance of undercover paved areas and environmental maintenance to yard car park and walkways	Order placed		2.50
14/077	Clear all gullies and jet through foul and surface water drains to yard, car park and undercover walkway	Work programmed for second half of financial year.		0.75
14/078	Redecoration of walls, ceilings gates and railings to undercover walkway	Complete		2.00
14/079	Clean and change lamps under canopy	Order placed		0.50

	Loughton Way, Buckhurst Hill (142 to 164)			
14/080	Environmental maintenance	Order placed		0.40
	Lower Queens Road, Buckhurst Hill (1, 4, 5 & 8)			
14/081	Redecoration of walls, ceilings and metalwork to undercover walkway	Complete		0.80
	and railings to side of parade			
	Market Square, Waltham Abbey (15 to 19)			
14/082	Clear all gullies and jet through surface water and foul drains to yard	Work programmed for second half of financial		0.40
	and paved areas	year.		
14/083	Clean and change lamps under canopy			1.75
	Parklands Coopersale (28 to 31)			
14/084	Clear all gullies and jet through surface water drains to yard and	Work programmed for second half of financial		0.25
	paved areas	year.		
14/085	Environmental maintenance	Work programmed for second half of financial		0.30
		year.		
	Pyrles Lane, Loughton (34 to 52)			
14/086	Preservative treatment to fences and gates and redecoration of	Order placed		3.00
	garage doors			
	Roundhills, Waltham Abbey (74 to 82)			
14/087	Clean and change lamps under canopy, end floodlight and yard	Work programmed for second half of financial		0.60
	lighting	year.		
	The Broadway, Loughton (11 to 73 & 12 to 82)			
14/088	Environmental Maintenance	Anticipated Completion March 2014		2.25
	The Street, High Ongar (48 & 50)			
14/089	Decoration, including minor overhaul of roof and anti-slip coating to	Order placed		6.25
	stairs			
	83 Loughton Way, Buckhurst Hill, Dentist Surgery			
14/090	Partial repointing of external walls and external redecoration	Complete		3.25
	including safe access for working at height			
			7.00	33.55
	Environmental improvement schemes			
CP118	Upshire Road Shops improvement scheme	At the request of Housing Services work	64.50	0.00
		moved to 2014/15		
	General Improvement Areas			
	Alfred Road, Buckhurst Hill			
14/091	Environmental maintenance	Order placed		1.50

14/092	Clear all gullies and jet through surface water drains to road areas	Work programmed for second half of financial		0.50
		year.		
	Woollard Street, Waltham Abbey			
14/093	Environmental maintenance	Order placed		0.50
				2.50
	Health & Safety Works			
14/094	Public building electrical testing, fire precaution requirements, fire fighting equipment servicing, asbestos management, water treatment works, amendments to statutory regulations	Orders placed and on going		8.00
	Contingency Fund			
CP101	Capital Contingency	Anticipated Completion March 2014	36.20	
14/095	Emergency Repairs	Anticipated Completion March 2014		5.00
			36.20	5.00
	Total £	Approved 2013/14 Expenditure	913.68	383.69
		Expenditure either transferred to 2014/15 or removed from the programme	402.50	78.36
	Total £	Anticipated Expenditure	511.18	305.33

Status definitions:

- 1 Health & Safety & Legislative implications.
- 2 Essential Work Major repairs to fabric and building services that may result in a loss of service provision or loss of income.
- 3 Works Commenced Commenced on a phased basis
- 4 Investment in Carbon Reduction & Renewable Energy
- 5 Desirable Work Repairs to fabric and building services.
- 6 Repair work too expensive cheaper to sell asset and rent back.
- 7 HRA

ltem Ref	Items for consideration in years 2014/15	Status * = Energy Saving	Capital Fund £000			Remarks
-				DDF	HRA	
	ffices, Epping					
	cal/Mechanical					
CP008	Photovoltaic Panel on the Main Building, Condor Building and Rear Extension, including pre work protection.	4*	180.00			This scheme was introduced to the Capital programme a few years ago. At the time it was considered that the technology had not attained a standard to consider the investment. It is now considered that the technology is sound and available. The budget covers preparing the roofs, prior to installation and the purchase and installation of the equipment.
CP113	Electrical load management infrastructure	2&3	11.00			To reduce risk of disruption to operations as a result of external power failure.
CP147	Fire Alarm – New Loops and Cards	1&3	16.00			The existing fire alarm requires upgrading in order to facilitate additional detectors to increase fire protection coverage of the complex.
CP146	Fire Alarm – Replacement Smoke and Heat Detection Loop 4 and 5	1&3	11.00			The existing smoke detectors have reached the end of their effective/design life
CP149	Trend Building Services - Software upgrade	4*	11.00			As the Council's energy is more closely managed and reductions made, it becomes necessary to continue with "fine tuning" of the energy management systems to continue to make energy spend savings. In order to achieve this, the Trend Building Management control strategy requires more detailed facilities. Further energy savings can be achieved by this provision
CP150	Daikin - Interface upgrade	4*	10.00			In a similar vein to the preceding item, further savings can be made by more accurate control of energy management and automation of air conditioning loads. Further energy savings can be achieved by this provision

ltem Ref	Items for consideration in years 2014/15	Status * = Energy Saving	Capital Fund £000	Revenue Fund £000		Remarks
				DDF	HRA	
	Boiler House replacement pumps	2&4	27.50			Existing boiler main pumps are obsolete and units require replacement
	Replacement of failing lighting fittings in offices in the Conder building phased programme	2&4*	20.00			The lighting units in the Conder building are failing and replacement parts are no longer available. The use of LED lighting will reduce the carbon footprint and energy consumption.
	Replacement of lighting in offices in the Civic Building inc 323 House with LED lighting - phased programme	2&4*	20.00			The lighting units in the Main building are failing and replacement parts are no longer available. The use of LED lighting will reduce the carbon footprint and energy consumption.
CP137	Electric, Gas and Main MWS Smart Metering	4*	15.00			The provision will enable the Council to better monitor electric, gas & water usage at all times, and manage the resource from the information gained, leading to reductions in utilities usage
	Plant Room 3 - Replacement AC compressor unit	2	20.00			Existing unit which serves the 2 no Committee Rooms, the Members Suite and the Staff Recreation Room is at the end of its design life and has failed on several occasions.
	Emergency Lighting Replacement & Battery Replacements - phased programme.	1		5.00		Health & Safety - The existing batteries in the emergency lights are reaching the end of their life expectancy
Main B	uilding (Internal)					
	Refurbish 1st floor kitchen	5		6.00		This kitchen is used on a daily basis for making refreshments for meetings, senior management and members.
	Partial replacement of worn floor finishes to offices, common and public areas	1		1.00		Coverings require replacement to prevent accidents and maintain standards
15/003	Partial redecoration of offices, common and public areas	5		6.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
15/004	Renew floor mats to all entrances	1		1.65		Mats require replacement to prevent accidents and maintain standards
Main B	uilding (External)					
CP155	Part DDA Compliance. Part resolution of Security problems. Provision of automatic opening doors at the main entrance.	1*	15.00			The main entrance has deteriorated. There is a large gap between the doors which gives no protection from the weather. The doors require replacement to comply with accessibility legislation. Their replacement will also result in energy savings.

ltem Ref	Items for consideration in years 2014/15	Status * = Energy Saving	Capital Fund £000	Revenue Fu	ind £000	Remarks
				DDF	HRA	
	Replacement of the concrete seating at the front of the building with 2 tier brick planters.	1	20.00			The concrete seating area was constructed in 1988. The original seating had a poor finish and a stone screed was skimmed over the area. Over time, heavy wear and tear, in particular from skate boarders, has resulted in areas of the seating having to be repaired every couple of years. A number of attempts have been made to try and persuade the skate boarders not to use the seating but these have been unsuccessful. It is therefore proposed to replace the seating with 2 levels of brick planters. This will lead to a reduction in annual maintenance costs.
	1 of 2 Replacement of the windows in the Main Building. South and West facing elevations	1&2*	135.00			The existing windows in the main building are suffering from rainwater ingress and poor draught proofing. The level of insulation offered by the double glazed units is to the original standard so heat loss through the glass is high. The original manufacturer of the windows no longer exists so spare parts for maintenance are no longer available. Their replacement will result in a further energy savings.
	Brickwork and hopper repairs to parapet walls including access lorry boom and operator for safe working at height	5		8.00		Carried forward from 2013/14. This work has been carried forward because it includes working at height. If the window replacement project was approved there would be a saving, by using the same scaffolding for these and 3 other projects.
	Reline lead valley around council chamber where split and defective and water is now seeping through to the roof deck below. Overcoat with proprietary system numerous splits, cracks, holes and the like to roof sheets, valley gutters, flashings, joints and details	2	15.00			Failure to attend to water ingress will result in internal flooding and lead to decay of structural elements
14/003	Reseal joints to parapet wall coping stones	2		6.00		Carried forward from 2013/14. This work has been carried forward because it includes working at height. If the window replacement project was approved there would be a saving, by using the same scaffolding for these and 3 other projects.
	High level decoration to steelwork - North and South elevations inc for scaffolding for safe working at height	5		7.00		Carried forward from 2013/14. This work has been carried forward because it includes working at height. If the window replacement project was approved there would be a saving, by using the same scaffolding for these and 3 other projects.

ltem Ref	Items for consideration in years 2014/15	Status * = Energy Saving	Capital Fund £000	Revenue Fu	ınd £000	Remarks
				DDF	HRA	
DF210	Reseal / remastic 2nd floor windows, inc for scaffolding for safe working at height	2		49.00		Carried forward from 2013/14. This work has been carried forward because it includes working at height. If the window replacement project was approved there would be a saving, by using the same scaffolding for these and 3 other projects.
Conde	r Building & Rear Extension (Internal)					
	Partial replacement of suspended ceilings	1		10.00		Existing ceiling tiles and support grids are beyond reasonable economic repair
15/007	Partial replacement of worn floors	1		3.75		Coverings require replacement to prevent accidents and maintain standards
15/008	Partial redecoration of offices - Conder	5		4.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
15/009	Partial redecoration of offices - Rear Extension	5		3.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
Conde	Building & Rear Extension (External)					
CP132	Replacement of degraded felt in gutters, soffits/fascias. Clear out gutters and replace slipped slates. Including for scaffolding/safe access for working at height.	2	25.00			Carried forward from 2013/14. This work has been carried forward because it includes working at height. If the solar panels progress then there would be a saving, by using the scaffolding for both these projects.
15/010	Redecoration and timber treatment	2		4.25		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
			551.50	114.65		
Homno	II Street Offices (External)					
	Repoint side elevation of chimney stack facing sports centre including access tower for safe working at height	2		1.50		Inadequate pointing of mortar joints will result in moisture ingress leading to brickwork failure
15/012	Drainage jetting	2		0.75		Risk of blockage if not undertaken
			0.00	2.25		
Epping	Depot					
	Basic standard of repair - Health & Safety requirements	1&7			6.50	Work required to comply with Health & Safety and Statutory Legislation
			0.00	0.00	6.50	

ltem Ref	Items for consideration in years 2014/15	Status * = Energy Saving	Capital Fund £000			Remarks
				DDF	HRA	
	on Road Depot (External)					
15/014	Basic standard of repair - Health & Safety requirements	1		3.75		Work required to comply with Health & Safety and Statutory Legislation.
15/015	Environmental maintenance	1		0.50		General clearance of weeds, debris and litter. Controls vermin and maintains fire exit routes
			0.00	4.25		
Town	l nead Depot (External)					
	Basic standard of repair - Health & Safety	1		3.00		Work required to comply with Uselth 9 Sefety and Statutony
	Environmental maintenance	1		1.20		Work required to comply with Health & Safety and Statutory General clearance of weeds, debris and litter. Controls vermin and maintains fire exit routes
15/018	Watercourse maintenance.	1		2.50		Health & Safety - Watercourse requires clearing annually to prevent flooding and control vermin
15/019	Redecorate including minor repairs	5		5.50		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
			0.00	12.20		
North	 Neald Airfield					
	l Tower (Internal)					
	Partial redecoration of offices	5		4.00		Decoration requires regular maintenance to minimise
		5		4.00		deterioration through wear and tear and to maintain visual standards
Buildir	g 240 - Fire Station (Internal)					
15/021	Clean and change lights	1		0.75		Health & Safety - Failing light fittings and general dirty condition requires a bulk clean and change
	stics Centre (structure, external and roof only)					
	Maintenance of fire escape routes including clearance of vegetation	1		0.30		Health & Safety requirement
15/023	Clear gullies and drainage channels to car park	2		0.25		Risk of blockage if not undertaken
				5.30		
Nurser	l y, Pyrles Lane, Loughton					
	Basic standard of repair - Health & Safety requirements	1	0.00	3.00		Work required to comply with Health & Safety and Statutory Legislation
			0.00	3.00		
l			ļ			
Museu	m, Waltham Abbey (External)					

ltem Ref	Items for consideration in years 2014/15	Status * = Energy Saving	Capital Fund £000			Remarks
				DDF	HRA	
15/025	Redecorate front/side elevations	5		5.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
Museur	n, Waltham Abbey (Internal)					
15/026	Maintenance of boiler	2	0.00	0.50 5.50		Ensures continued service, efficiency and fuel economy
Public ⁻	Foilet, High Street, Ongar					
15/027	Jet through foul water drainage system	2		0.15		Risk of blockage if not undertaken
	Remove failing electric security releases (automatically lock doors 'out of hours') to entrance doors. Modify door frames and supply and install new heavy duty electric releases.	1		1.50		Failure to replace releases may result in premises being open during evenings leading to potential anti social behaviour and vandalism
			0.00	1.65		
Industr	ial Estates					
Brooke	r Road Industrial Estate, Waltham Abbey					
15/029	Environmental maintenance	1		2.80		General clearance of weeds, debris and litter. Controls vermin
15/030	Watercourse maintenance.	1		1.50		Health & Safety - Watercourse requires clearing annually to prevent flooding and control vermin
15/031	Patch repair and white line lower end car park	1		4.75		This item was scheduled for 2013/14, but due to Council's riparian responsibilities on a watercourse that flows along the northern boundary, the budget was diverted to deal with this.
			0.00	9.05		
Oakwo	od Hill Industrial Estate Workshop Units					
CP005	Upgrade Industrial Units	2	300.00			See report
15/032	Environmental maintenance	1		1.50		General clearance of weeds, debris and litter. Controls vermin and maintains fire exit routes
15/033	Redecoration of timberwork and metal walkway	5		4.50		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
15/034	Clear debris from surface water drainage channels/drains	2		1.00		Risk of blockage if not undertaken
			300.00	7.00		
Sports	Centres					

ltem Ref	Items for consideration in years 2014/15	Status * = Energy Saving	Capital Fund £000			Remarks
				DDF	HRA	
15/075	Detailed condition survey of the 4 Leisure Facilities	2		49.20		To assess the condition and life expectancy, to produce an expenditure profile to keep the buildings in a good to satisfactory condition. This id to form part of the Council's Leisure Stratagy.
				49.20		
Epping	Sports Centre					
Externa						
	Resurface car park including reline marking	1	13.00			Surfacing in poor condition and becoming a potential Health & Safety risk. Brought forward from 2013/14 at the request of the Leisure Contract Monitoring Board.
15/035	Drainage jetting	2		0.75		Risk of blockage if not undertaken
			13.00	0.75		
Lought	on Leisure Centre					
Externa						
	Drainage jetting	2		0.75		Risk of blockage if not undertaken
	Redecorate railings to yard/access road	5		1.20		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
	Redecorate steel columns, beams and tie bars above main entrance	5		2.80		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
	Prepare and apply decorative preservative treatment to exposed timber glulam beams	5		5.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
	Renew perished movement joints to wall and around penetrations into building	5		5.25		Mastic sealed movement joints have deteriorated substantially. Water ingress would cause damage to the building fabric
	Clean and restore stained blockwork and reconstituted stone including safe access for working at height	5		7.00		Clean stonework to maintain the external stonework to an acceptable standard. Carried forward from year 1 of Planned Maintenance Programme.
			0.00	22.00		
Ongar I	_eisure Centre					
Externa						
15/042	Clear all gullies and jet through surface water drains to yards, car parks and walkways including emptying petrol interceptors and cleaning filters	2		1.75		Risk of blockage if not undertaken

ltem Ref	Items for consideration in years 2014/15	Status * = Energy Saving	Capital Fund £000	Revenue Fu	ind £000	Remarks
				DDF	HRA	
15/043	Lamp replacements to street lights	1		0.50		Health & Safety - To maintain a level of security and public safety
15/044	Patching/Repairs to roof, copings and movement joints	2		4.50		Roof coverings are nearing the end of their life span. Water ingress would cause damage to the building fabric
15/045	Reline markings to car park	5		4.25		Line markings are fading and require attention to ensure parking is controlled
			0.00	11.00		
Waltha	m Abbey Swimming Pool					
Externa	al					
CP159	Resurface car park and access road including re line marking	2	37.00			Surfacing in poor condition and becoming a potential Health & Safety risk
15/046	External redecoration of entrance wall	5		0.50		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
15/047	Drainage jetting	2		0.75		Risk of blockage if not undertaken
	Redecorate previously decorated surfaces, fasciae, soffits, timber and metalwork	5		5.75		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
			37.00	7.00		
Limes (Centre (Internal)					
CP160	Install a new access point to the plant room, including diverting statutory services, to avoid going through doctor's consulting room.	2	25.00			Access to the plant room, which houses control panels and meters, is through the Doctor's consulting room. This makes access for the maintenance contractors and utility companies difficult.
CP161	Acoustic reduction in both halls	2	10.00			Sound reverberation in both halls is leading to excessive noise and affecting users (includes safe acces for working at height)
	Knock through wall between 2 halls storage cupboards	2		2.50		Lettings of the small and large halls are complaining that access to equipment stored in the cupboards of the opposite hall is difficult when that hall is occupied.
			35.00	2.50		
Counci	I Owned Shopping Parades					
	s Lane, Loughton (58 to 76)					
	Drainage Jetting	2		0.75		Risk of blockage if not undertaken
15/051	Environmental maintenance	1		0.80		General clearance of weeds, debris and litter. Controls vermin

ltem Ref	Items for consideration in years 2014/15	Status * = Energy Saving	Capital Fund £000			Remarks
				DDF	HRA	
15/052	Clean and change lamps to wall mounted fittings	1		0.50		Health & Safety - To maintain a level of security and public safety
				2.05		
Hillhou	se, Waltham Abbey (1 to 12)					
	Clear all gullies and jet through surface water drains to yards, car park and walkways	2		0.50		Risk of blockage if not undertaken
				0.50		
	Avenue, Chigwell (548 to 562)					
	Pressure washing and general maintenance of undercover paved areas and environmental maintenance to yard car park and walkways	1		2.50		Health & Hygiene - removal of chewing gum, litter, weeds, urine etc.
	Clear all gullies and jet through foul and surface water drains to yard, car park and undercover walkway	2		0.75		Risk of blockage if not undertaken
	Carry out repairs to flat roof including fascias, soffits and edge trims	5		3.00		Areas of the roof have had temporary repairs. Water ingress would cause damage to the building fabric
			0.00	6.25		
	on Way, Buckhurst Hill (142 to 164)					
15/057	Environmental maintenance	1		0.40		General clearance of weeds, debris and litter. Controls vermin
15/058	Preservative treatment to fences and gates	5		2.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
				2.40		
Lower (Queens Road, Buckhurst Hill (1, 4, 5 & 8)					
15/059	Clean and change lamps to wall and ceiling mounted light fittings	1		0.50		Health & Safety - To maintain a level of security and public safety
				0.50		
	Square, Waltham Abbey (15 to 19)					
	Clear all gullies and jet through surface water and foul drains to yard and paved areas	2		0.40		Risk of blockage if not undertaken
				0.40		

ltem Ref	Items for consideration in years 2014/15	Status * = Energy Saving	Capital Fund £000			Remarks
				DDF	HRA	
	ds Coopersale (28 to 31)	-				
	Clear all gullies and jet through surface water drains to yard and paved areas	2		0.25		Risk of blockage if not undertaken
15/063	Environmental maintenance	1		0.30		General clearance of weeds, debris and litter. Controls vermin
	Clean and change lamps under canopy and to floodlights	1		0.40		Health & Safety - To maintain a level of security and public safety
				0.95		
	Lane, Loughton (34 to 52)					
14/065	Overlay cracked asphalt roofs to rear extensions	2		4.40		Areas of roof coverings are at the end of their life span and a number of temporary repairs have been undertaken. Water ingress would cause damage to the building fabric
			0.00	4.40		
Round	nills, Waltham Abbey (74 to 82)					
	Redecoration of front canopy, staircase elevation, bollards and barriers	5		2.50		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
				2.50		
	oadway, Loughton (11 to 73 & 12 to 82)					
15/067	Redecoration of undercover walkway and balcony fasciae to shops.	5		17.00		Redecoration of the undercover walkway leading to Vere Road and balcony fasciae, to enhance the area.
15/068	Environmental Maintenance	1		2.25		General clearance of weeds, debris and litter. Controls vermin
			0.00	19.25		
	I Improvement Areas (GIAS)					
	Road, Buckhurst Hill					
	Environmental maintenance	1		1.50		General clearance of weeds, debris and litter. Controls vermin
	Carry out isolated repairs to close boarded timber fences and apply preservative treatment (section to Alfred Rd)	5		5.00		Land management responsibilities under the Highways Act
15/071	Clear all gullies and jet through surface water drains to road areas	2		0.50		Risk of blockage if not undertaken
				7.00		
Woolla	rd Street, Waltham Abbey					
	Environmental maintenance	1		0.50		General clearance of weeds, debris and litter. Controls vermin

ltem Ref	Items for consideration in years 2014/15	Status * = Energy Saving	Capital Fund £000	Revenue Fu	ınd £000	Remarks
				DDF	HRA	
				0.50		
Health	& Safety Works					
	Public building electrical testing, fire precaution requirements, fire fighting equipment servicing, asbestos management, water treatment works, amendments to statutory regulations	1		8.00		Work required to comply with Health & Safety and Statutory Legislation
				8.00		
Contin						
	Capital Contingency	1	25.00			To cover unforseen items and other works that do not fall into categories 1 to 4
15/074	Emergency Repairs	1		5.00		To cover unexpected works on the Revenue programme
			25.00	5.00		
	Funding for the year 2014/15		961.50	317.00	6.50	
	Total Revenue		301.30	517.00	323.50	
	Current DDF Approved Budget				39.00	
	Grand Total (Revenue)				284.50	
	Less CSB allocated				118.00	
	Less HRA allocated				6.50	
	Net DDF requirement for 2014/15				160.00	
	Capital schemes - additional funding		92.50			
	Budget Approved todate		619.00			
	Recommended Reprofiling		338.00			
	Total Capital expenditure		1049.50			

Facilities Management 2015/16, 2016/17 & 2017/18 Programme of Work

Status definitions:

- 1 Health & Safety & Legislative implications.
- 2 Essential Work Major repairs to fabric and building services that may result in a loss of service provision or loss of income.
- 3 Works Commenced Commenced on a phased basis.
- 4 Investment in Carbon Reduction & Renewable Energy.
- 5 Desirable Work Repairs to fabric and building services.
- 6 Repair work too expensive cheaper to sell asset and rent back.

7 HRA.

ltem Ref	Future items for consideration in years , 2015/16, 2016/17 & 2017/18	Status [*] = Energy Saving	Capital Fund (GF) £000	Revenue	£000	Remarks
				DDF	HRA	
	Year 2015/16					
	ffices, Epping al/Mechanical					
	Electrical load management infrastructure	2&3	11.00			To reduce risk of disruption to operations as a result of external power failure.
16/001	Fire Alarm – New Smoke and Heat Detection	1&3	16.00			Additional fire cover has been recommended by the Council's insurer
	Fire Alarm – Replacement Smoke and Heat Detection Loop 3	1&3	5.00			The existing smoke detectors have reached the end of their effective/design life
	Tower Toilet Fresh Air supply & Extract air handling units replacement	2	14.30			The existing air handling units have reached the end of their effective life
CP137	Electric, Gas and Main MWS Smart Metering		10.00			The provision will enable the Council to better monitor electric, gas & water usage at all times, and manage the resource from the information gained, leading to reductions in utilities usage and hence reducing utility service costs and carbon footprint.
	Plant Room 3 - Replacement supply/extract fans to Council Chamber	2&4*	40.00			The existing air handling units have reached the end of their effective life
16/005	Homefield House - Upgrades to power lighting and fire alarms	2	22.00			The existing systems have exceeded their expected life and do not comply with modern legislation. The fire alarm is not linked to the rest of the complex
	Replacement of failing lighting fittings in offices in the Conder building - phased programme.	2&4*	20.00			The lighting units in the Conder building are failing and replacement parts are no longer available. The use of LED lighting will reduce the carbon footprint and energy consumption.

ltem	Future items for consideration in years ,	Status	Capital	Revenue	£000	Remarks
Ref	2015/16, 2016/17 & 2017/18	[*] = Energy Saving	Fund (GF) £000			
	Replacement of lighting in offices in the Civic Building inc 323 House with LED lighting phased programme.	2&4*	20.00			The lighting units in the Main building are failing and replacement parts are no longer available. The use of LED lighting will reduce the carbon footprint and energy consumption.
	Phased replacement of Electrical Power Distribution Boards / MCB's MCBO's due to life extinction.	2	10.00			This provision is programmed to ensure replacement of equipment before failure, which would have an impact on the Council's service provision due to loss of power occurring.
	Emergency Lighting Replacement & Battery Replacements	1		5.00		Health & Safety - The existing batteries in the emergency lights are reaching the end of their life expectancy
	Statutory Portable & Transportable Appliance Testing & Certification	1		11.00		Health and Safety - to comply with statutory regulations
Main B	uilding (External)					
16/007	Redecoration of general timber surfaces	5		4.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
16/008	Jet through all foul and surface water drains	2		4.50		Risk of blockage if not undertaken
	2 of 2 Replacement of the windows in the Main Building, East and North facing and link bridge.	1&2*	160.00			The existing windows in the main building are suffering from rainwater ingress and poor draught proofing. The level of insulation offered by the double glazed units is to the original standard so heat loss through the glass is high. The original manufacturer of the windows no longer exists so spare parts for maintenance are no longer available. Their replacement will result in a large energy saving and improved working conditions.
	Specialist cleaning of stonework and rendered façades.	5		10.00		Clean stonework of ceremonial staircase and walls to complement the remodelling of the building.
	uilding (Internal)					
	Refurbish 1st floor north Toilets	4*	37.00			Aging facilities require refurbishment and upgrading
	Refurbish ground floor north toilets, including accessible toilet	4*	51.00			Aging facilities require refurbishment and upgrading
	Partial replacement of worn floor finishes to offices, common and public areas	1		1.00		Coverings require replacement to prevent accidents and maintain standards
16/014	Partial redecoration of offices, common and public areas	5		6.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
16/015	Renew and repair window blinds	5		4.00		The opportunity to replace broken window blinds
16/016	Repaint and decorate recreation room	5		1.25		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards

ltem	Future items for consideration in years ,	Status	Capital	Revenue	£000	Remarks
Ref	2015/16, 2016/17 & 2017/18	* = Energy Saving	Fund (GF) £000			
	Redecorate Committee Room 1+2	5		1.50		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
	Building & Rear Extension (Internal)					
16/018	Partial replacement of suspended ceilings	1		10.00		Existing ceiling tiles and support grids are beyond reasonable economic repair
16/019	Partial replacement of worn floors	5		3.75		Coverings require replacement to prevent accidents and maintain standards
16/020	Partial redecoration of offices	5		4.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
			416.30	66.00		
Hemna	Il Street Offices (External)					
	Drainage jetting	2		0.75		Risk of blockage if not undertaken
	Redecoration to main building	5		10.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
				10.75		
Epping	Denot					
	Basic standard of repair - Health & Safety requirements	1			6.50	Work required to comply with Health & Safety and Statutory Legislation
				0.00	6.50	
Longot	an Dead Denet Leventern (Externel)					
	on Road Depot, Loughton (External) Depot environmental maintenance	1		0.50		General clearance of weeds, debris and litter. Controls vermin and maintains fire exit routes
	Basic standard of repair - Health & Safety requirements	1		3.75		Work required to comply with Health & Safety and Statutory Legislation
				4.25		
Townm	ead Depot (External)					
	Basic standard of repair - Health & Safety	1		3.00		Work required to comply with Health & Safety and Statutory
	requirements			0.00		Legislation
	Environmental maintenance	1		1.20		General clearance of weeds, debris and litter. Controls vermin and maintains fire exit routes
16/028	Watercourse maintenance	1		2.50		Health & Safety - Watercourse requires clearing annually to prevent flooding and control vermin
				6.70		

ltem Ref	Future items for consideration in years , 2015/16, 2016/17 & 2017/18	Status [*] = Energy Saving	Capital Fund (GF) £000	Revenue	£000	Remarks
North V	L Veald Airfield					
	stics Centre (structure, external and roof only)					
	Maintenance of fire escape routes including clearance	1		0.30		Health & Safety requirement
	of vegetation			0.30		ricalin & Salety requirement
				0.30		
Nurser	y, Pyrles Lane, Loughton					
	Basic standard of repair - Health & Safety requirements	1		3.00		Work required to comply with Health & Safety and Statutory Legislation
				3.00		
Museu	n, Waltham Abbey					
Interna						
	Maintenance of boiler	2		0.50		Ensures continued service, efficiency and fuel economy
	Partial replacement of worn floor finishes to offices and public areas	1		2.00		Coverings require replacement to prevent accidents and maintain standards
16/033	Partial redecoration of offices and public areas	5		3.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
				5.50		
Public	L Toilet, High Street, Ongar					
	Jet through foul water drainage system	2		0.15		Risk of blockage if not undertaken
10/001				0.15		
Industr	ial Estates					
Brooke	r Road Industrial Estate, Waltham Abbey					
16/035	Environmental maintenance	1		2.80		General clearance of weeds, debris and litter. Controls vermin
16/036	Watercourse maintenance.	1		1.50		Health & Safety - Watercourse requires clearing annually to prevent flooding and control vermin
Oakwo	od Hill Industrial Estate Workshop Units					
	Environmental maintenance	1		1.50		General clearance of weeds, debris and litter. Controls vermin and maintains fire exit routes
16/038	Electro-hydraulic lift installation	1	77.00			Health & Safety - Lift is in need of refurbishment to ensure the safety of the users and also to bring in line with DDA regulations
			77.00	5.80		

ltem	Future items for consideration in years ,	Status	Capital	Revenue	£000	Remarks
Ref	2015/16, 2016/17 & 2017/18	* = Energy Saving	Fund (GF) £000			
Epping	Sports Centre	eug				
Externa						
	Drainage jetting	2		0.75		Risk of blockage if not undertaken
	Redecoration including minor repairs	5		2.50		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
				3.25		
	on Leisure Centre					
Externa						
	Drainage jetting	2		0.75		Risk of blockage if not undertaken
	General overhaul of upstands, flashings, details and fixings	2		4.00		Areas of the roof have had temporary repairs. Water ingress would cause damage to the building fabric
16/043	Apply preservative treatment to windows and doors of Octagon building	5		1.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
				5.75		
Ongar	Leisure Centre					
Externa	al					
16/044	Clear all gullies and jet through surface water drains to yards, car parks and walkways including emptying petrol interceptors and cleaning filters	2		1.75		Risk of blockage if not undertaken
16/045	Lamp replacement to street lights	1		0.50		Health & Safety - To maintain a level of security and public safety
				2.25		
Waltha	m Abbey Swimming Pool					
Externa						
	External redecoration of entrance wall	5		0.50		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
16/047	Drainage jetting	2		0.75		Risk of blockage if not undertaken
				1.25		
Counci	I Owned Shopping Parades					
	s Lane, Loughton (58 to 76)					
	Drainage Jetting	2		0.75		Risk of blockage if not undertaken
	Environmental maintenance	1		0.80		General clearance of weeds, debris and litter. Controls vermin

ltem	Future items for consideration in years ,	Status	Capital	Revenue	£000	Remarks	
Ref	2015/16, 2016/17 & 2017/18	* = Energy	Fund (GF)				
		Saving	£000				
16/050	Redecoration of extensions	5		2.50		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards	
Hillhou	se, Waltham Abbey (1 to 12)						
16/051	Clear all gullies and jet through surface water drains to yards, car park and walkways	2		0.50		Risk of blockage if not undertaken	
Limes	Avenue, Chigwell (548 to 562)						
16/052	Pressure washing and general maintenance of undercover paved areas and environmental	1		2.50		Health & Hygiene - removal of chewing gum, litter, weeds, urine etc.	
16/053	Clear all gullies and jet through foul and surface water drains to yard, car park and undercover walkway	2		0.75		Risk of blockage if not undertaken	
	Redecoration of walls, ceilings gates and railings to undercover walkway	5		2.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards	
	on Way, Buckhurst Hill (142 to 164)						
	Environmental maintenance Queens Road, Buckhurst Hill (1, 4, 5 & 8)	1		0.40		General clearance of weeds, debris and litter. Controls vermin	
	Redecoration of walls, ceilings and metalwork to undercover walkway and railings to side of parade	5		0.80		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards	
Market	Square, Waltham Abbey (15 to 19)						
	Clear all gullies and jet through surface water and foul drains to yard and paved areas	2		0.40		Risk of blockage if not undertaken	
Parklar	nds Coopersale (28 to 31)						
16/058	Clear all gullies and jet through surface water drains to yard and paved areas	2		0.25		Risk of blockage if not undertaken	
16/059	Environmental maintenance	1		0.30		General clearance of weeds, debris and litter. Controls vermin	
16/060	Redecoration of front canopy and common areas	5		4.75		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards	
	oadway, Loughton (11 to 73 & 12 to 82)						
	Environmental Maintenance	1		2.25		General clearance of weeds, debris and litter. Controls vermin	
				18.95			
	I Improvement Areas (GIAS)						
	Road, Buckhurst Hill						
16/062	Environmental maintenance	1		1.50		General clearance of weeds, debris and litter. Controls vermin	

ltem	Future items for consideration in years ,	Status	Capital	Revenue	£000	Remarks
Ref	2015/16, 2016/17 & 2017/18	* = Energy Saving	Fund (GF) £000			
	Clear all gullies and jet through surface water drains to road areas			0.50		Risk of blockage if not undertaken
	Carry out isolated repairs to close boarded timber fences and apply preservative treatment (section to Alfred Rd)	5		5.00		Land management responsibilities under the Highways Act
	Carry out isolated repairs to Private Road and Unregulated Parking Area (section to Alfred Rd)	1		1.00		Health & Safety: Carry out repairs to potholes and damaged kerbs.
Woolla	rd Street, Waltham Abbey					
16/065	Environmental maintenance	1		0.50 8.50		General clearance of weeds, debris and litter. Controls vermin
Chiawe	II Row Recreation Ground					
16/066	Renewal of timber kick boards to court areas and replacement of 2 Nr timber gates and posts at entrance	5		5.00		Exposure to elements, wear and tear and vandalism results in the need for replacement
				5.00		
Health	& Safety Works					
16/067	Public building electrical testing, fire precaution requirements, fire fighting equipment servicing, asbestos management, water treatment works,	1		8.00		Work required to comply with Health & Safety and Statutory Legislation
				8.00		
Conting	gency					
	Capital Contingency	1	25.00			To cover status 5 and unexpected works on the Capital programme
16/068	Emergency Repairs	1	25.00	5.00 5.00		To cover unexpected works on the Revenue programme
	Funding for the year 2015/16		518.30	160.40	6.50	
	Total Revenue				166.90	
	Current DDF Approved Budget				11.00	
	Grand Total (Revenue)				155.90	
	Less CSB allocated				118.00	
	Less HRA allocated				6.50	
	Net DDF requirement for 2015/16				31.40	
	Capital schemes - additional funding		193.30			
	Budget Approved todate		332.00			
	Recommended Reprofiling		0.00			

ltem Ref	Future items for consideration in years , 2015/16, 2016/17 & 2017/18	Status [*] = Energy Saving	Capital Fund (GF) £000	Revenue	£000	Remarks
	Total Capital expenditure		525.30			
	Year 2016/17					
	ffices, Epping					
	cal/Mechanical					
	Replacement of failing lighting fittings in offices in the Conder building - phased programme.	2&3*	20.00			The lighting units in the Conder building are failing and replacement parts are no longer available. The use of LED lighting will reduce the carbon footprint and energy consumption.
	Replacement of lighting in offices in the Civic Building inc 323 House with LED lighting - phased programme.	2&3*	20.00			The lighting units in the Main building are failing and replacement parts are no longer available. The use of LED lighting will reduce the carbon footprint and energy consumption.
	New generator	2	55.00			The existing generator was installed in 1989; since then an increase in essential electrical power demand, results in the existing generator capacity being insufficient.
	Fire Alarm – New Smoke and Heat Detection	1&3	16.00			Additional fire cover has been recommended by the Council's
	Plant Room 2 - Replacement supply/extract fans to Member Suite	2	30.00			The existing air handling units have reached the end of their effective life.
17/004	Computer Suite 2 - Replacement AC units	2	55.00			The existing air conditioning unit is showing signs of failure, this needs replacing
17/005	Cash Suite - Air handling Unit	2	90.00			The existing air handling units have reached the end of their effective life.
	Phased replacement of Electrical Power Distribution Boards / MCB's MCBO's due to life extinction.	2	10.00			This provision is programmed to ensure replacement of equipment before failure, which would have an impact on the Council's service provision due to loss of power occurring.
	Statutory Testing of Electrical Installation & rectification of defects	1		20.00		Health and Safety - to comply with statutory regulations
	Emergency Lighting Replacement & Battery Replacements	1		5.00		Health & Safety - Existing batteries in the emergency scheme are reaching the end of their life expectancy.
17/007	UPS maintenance and battery replacement	2		2.50		To reduce risk of disruption to operations as a result of external power failure.
Main B	uilding (External)					
17/008	Redecoration of general metalwork surfaces, railings, handrails, gates and staircases	5		5.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
	uilding (Internal)					
	Refurbish Tower first floor toilets, including accessible toilets	4&5*	46.00			Aging facilities require refurbishment and upgrading

ltem	Future items for consideration in years ,	Status	Capital	Revenue	£000	Remarks
Ref	2015/16, 2016/17 & 2017/18	* = Energy Saving	Fund (GF) £000			
17/059	Refurbish Tower ground floor toilets, including accessible toilets	4&5*	49.00			Aging facilities require refurbishment and upgrading
17/009	Partial replacement of worn floor finishes to offices, common and public areas	1		1.00		Coverings require replacement to prevent accidents and maintain standards
17/010	Partial redecoration of offices, common and public areas	5		6.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
Conde	r Building & Rear Extension (Internal)					
17/011	Partial replacement of suspended ceilings	1		10.00		Existing ceiling tiles and support grids are beyond reasonable economic repair
17/012	Partial replacement of worn floors	5		3.75		Coverings require replacement to prevent accidents and maintain standards
17/013	Partial redecoration of offices	5		4.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
			391.00	57.25		
Homno	Il Street Offices (External)					
		2		0.75		Pick of blockage if not undertaken
	Drainage jetting	5		0.75		Risk of blockage if not undertaken
17/015	External redecoration to single storey section of building including timber windows, doors and glazed walls at ground floor level including minor repairs and redecorate metal railings, handrails and bollards	5		7.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
				7.75		
Epping	Depot					
	Basic standard of repair - Health & Safety requirements	1			6.50	Work required to comply with Health & Safety and Statutory Legislation
	· ·			0.00	6.50	
Lanost	on Road Depot, Loughton (External)					
17/017	Depot environmental maintenance	1		0.50		General clearance of weeds, debris and litter. Controls vermin and maintains fire exit routes
17/018	Basic standard of repair - Health & Safety requirements	1		3.75		Work required to comply with Health & Safety and Statutory Legislation
				4.25		
L						
Iownm	nead Depot (External)				l	

ltem	Future items for consideration in years ,	Status	Capital	Revenue	£000	Remarks	
Ref	2015/16, 2016/17 & 2017/18	* = Energy	Fund (GF)				
		Saving	£000				
17/019	Basic standard of repair - Health & Safety	1		3.00		Work required to comply with Health & Safety and Statutory	
	requirements					Legislation	
17/020	Environmental maintenance	1		1.20		General clearance of weeds, debris and litter. Controls vermin	
						and maintains fire exit routes	
17/021	Watercourse maintenance.	1		2.50		Health & Safety - Watercourse requires clearing annually to	
						prevent flooding and control vermin	
				6.70			
North V	Veald Airfield						
Gateho	use (External)						
	e Store (External)						
	Preservative treatment and redecoration to external	5		2.75		Decoration requires regular maintenance to minimise	
	timber fasciae, soffits, doors and panels					deterioration through wear and tear and to maintain visual	
						standards	
	stics Centre (structure, external and roof only)						
	Maintenance of fire escape routes including clearance	1		0.30		Health & Safety requirement	
	of vegetation					- · · · · · · · · · · · · · · · · · · ·	
	Clear all gullies and drainage channels to car park	2		0.25		Risk of blockage if not undertaken	
	areas and jet through surface water drainage			0.00			
	Preservative treatment to timber oil storage tank	5		0.60		Decoration requires regular maintenance to minimise	
	enclosure					deterioration through wear and tear and to maintain visual	
				3.90		standards	
				3.90			
Nurser	y, Pyrles Lane, Loughton						
	Basic standard of repair - Health & Safety	1		3.00		Work required to comply with Health & Safety and Statutory	
	requirements			0.00		Legislation	
				3.00			
Museu	m, Waltham Abbey						
Interna							
17/027	Maintenance of boiler	2		0.50		Ensures continued service, efficiency and fuel economy	
				0.50			
Public [*]	Toilet, High Street, Ongar						
	Jet through foul water drainage system	2		0.15		Risk of blockage if not undertaken	
				0.15			
L							
	ial Estates						
Brooke	r Road Industrial Estate, Waltham Abbey						

ltem	Future items for consideration in years ,	Status	Capital	Revenue	£000	Remarks
Ref	2015/16, 2016/17 & 2017/18	* = Energy Saving	Fund (GF) £000			
17/029	Environmental maintenance	1		2.80		General clearance of weeds, debris and litter. Controls vermin
17/030	Watercourse maintenance.	1		1.50		Health & Safety - Watercourse requires clearing annually to prevent flooding and control vermin
	od Hill Industrial Estate Workshop Units					
17/031	Environmental maintenance	1		1.50		General clearance of weeds, debris and litter. Controls vermin and maintains fire exit routes
			0.00	5.80		
	Sports Centre					
Externa		-				
17/032	Drainage jetting	2		0.75 0.75		Risk of blockage if not undertaken
Lought	on Leisure Centre					
Externa						
17/033	Drainage jetting	2		0.75 0.75		Risk of blockage if not undertaken
Ongar I	_eisure Centre					
Externa						
	Clear all gullies and jet through surface water drains to yards, car parks and walkways including emptying petrol interceptors and cleaning filters	2		1.75		Risk of blockage if not undertaken
17/035	Patching/Repairs of roof copings, Movement and Joints	2		4.50		Roof coverings are nearing the end of their life span. Water ingress would cause damage to the building fabric
17/036	Service and clean streetlights and replace lamps	1		1.50		Health & Safety - To maintain a level of security and public safety
	Apply preservative treatment to windows, doors and cladding	5		3.75		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
				11.50		
	m Abbey Swimming Pool					
Externa						
17/038	External redecoration of entrance wall	5		0.50		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
17/039	Drainage jetting	2		0.75		Risk of blockage if not undertaken
				1.25		

ltem Ref	Future items for consideration in years , 2015/16, 2016/17 & 2017/18	Status [*] = Energy Saving	Capital Fund (GF) £000	Revenue	£000	Remarks
Counci	Owned Shopping Parades					
	s Lane, Loughton (58 to 76)					
	Drainage Jetting	2		0.75		Risk of blockage if not undertaken
	Environmental maintenance	1		0.80		General clearance of weeds, debris and litter. Controls vermin
	se, Waltham Abbey (1 to 12)	•		0.00		
	Clear all gullies and jet through surface water drains to	2		0.50		Risk of blockage if not undertaken
	yards, car park and walkways	-		0.00		
	Avenue, Chigwell (548 to 562)					
	Resurface rear yard	2	10.00			Surfacing in poor condition and becoming a potential Health & Safety risk
	Pressure washing and general maintenance of undercover paved areas and environmental maintenance to yard car park and walkways	1		2.50		Health & Hygiene - removal of chewing gum, litter, weeds, urine etc.
	Clear all gullies and jet through foul and surface water drains to yard, car park and undercover walkway	2		0.75		Risk of blockage if not undertaken
Lought	on Way, Buckhurst Hill (142 to 164)					
	Environmental maintenance	1		0.40		General clearance of weeds, debris and litter. Controls vermin
Market	Square, Waltham Abbey (15 to 19)					
17/047	Clear all gullies and jet through surface water and foul drains to yard and paved areas	2		0.40		Risk of blockage if not undertaken
Parklar	ds Coopersale (28 to 31)					
	Clear all gullies and jet through surface water drains to yard and paved areas	2		0.25		Risk of blockage if not undertaken
	Environmental maintenance	1		0.30		General clearance of weeds, debris and litter. Controls vermin
Round	nills, Waltham Abbey					
	Mineral cap sheet overlay to front canopy felt roof	5	6.00			The existing roofing has reached the end of its design life.
	badway, Loughton (11 to 73 & 12 to 82)	-				
17/051	Environmental Maintenance	1		2.25		General clearance of weeds, debris and litter. Controls vermin
			16.00	8.90		
Enviror	imental improvement schemes					
CP118	Upshire Road Shops improvement scheme	5	64.50			Continuing environmental enhancement programme around Council owned shopping areas
			64.50			

ltem Ref	Future items for consideration in years , 2015/16, 2016/17 & 2017/18	Status [*] = Energy Saving	Capital Fund (GF) £000	Revenue	£000	Remarks
Gonora	I Improvement Areas (GIAS)					
	Road, Buckhurst Hill					
	Environmental maintenance	1		1 50		Canaral algorange of woods, debris and litter. Controls vermin
17/052	Environmental maintenance	1		1.50		General clearance of weeds, debris and litter. Controls vermin
17/053	Clear all gullies and jet through surface water drains to	2		0.50		Risk of blockage if not undertaken
	road areas					
Woolla	d Street, Waltham Abbey					
17/054	Environmental maintenance	1		0.50		General clearance of weeds, debris and litter. Controls vermin
				2.50		
Health	& Safety Works					
	Public building electrical testing, fire precaution	1		8.00		Work required to comply with Health & Safety and Statutory
	requirements, fire fighting equipment servicing,					Legislation
	asbestos management, water treatment works,					ő
	amendments to statutory regulations					
	, ,			8.00		
				0.00		
Conting	gency					
CP101	Capital Contingency	1	25.00			To cover status 5 and unexpected works on the Capital programme
17/056	Emergency Repairs	1		5.00		To cover unexpected works on the Revenue programme
17/057	Consultants report for 5 year programme	2		20.00		Condition survey and 5 year Planned Maintenance Report for 2017 to 2022
			25.00	25.00		
	Funding for the year 2016/17		496.50	147.95	6.50	
	Total Revenue				154.45	
	Current DDF Approved Budget				-23.00	
	Grand Total (Revenue)				177.45	
	Less CSB allocated				118.00	
	Less HRA allocated				6.50	
	Net DDF requirement for 2016/17				52.95	
	Capital schemes - additional funding		38.50		02.00	
	Budget Approved todate		298.00			
	Recommended Reprofiling		65.00			
	Total Capital expenditure		401.50			

ltem Ref	Future items for consideration in years , 2015/16, 2016/17 & 2017/18	Status [*] = Energy Saving	Capital Fund (GF) £000	Revenue	£000	Remarks
	Year 2017/18 (Pre Condition Survey Report 2016/17)					
	ffices, Epping					
	cal/Mechanical					
	Replacement of failing lighting fittings in offices in the Conder building.	2&4	20.00			The lighting units in the Conder building are failing and replacement parts are no longer available. The use of LED lighting will reduce the carbon footprint and energy consumption.
	Replacement of lighting in offices in the Civic Building inc 323 House with LED lighting	2&4	20.00			The lighting units in the Main building are failing and replacement parts are no longer available. The use of LED lighting will reduce the carbon footprint and energy consumption.
	Fire Alarm System - Major Upgrade of System Control and Amplifiers	1&3	10.00			The existing equipment has reached the end of their effective/design life
18/002	Fire Alarm System - Speaker Replacement	1&3	10.00			The existing fire alarm requires upgrading in order to facilitate additional detectors to increase fire protection coverage of the complex.
18/003	Plant Room 2 - Replacement supply/extract fans to internal office space	2&4*	12.00			The existing air handling units have reached the end of their effective life
18/004	Plant Room 3 - Replacement supply/extract fans to Staff Recreation area	2&4*	12.00			The existing air handling units have reached the end of their effective life
18/005	Replacement of Major Pumps to Boiler House.	2&4*	12.00			The existing air handling units have reached the end of their effective life
18/006	Phased replacement of Electrical Power Distribution Boards / MCB's MCBO's due to life extinction.	2	10.00			This provision is programmed to ensure replacement of equipment before failure, which would have an impact on the Council's service provision due to loss of power occurring.
	uilding (External)					
18/007	Redecoration of general timber surfaces	5		4.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
	uilding (Internal)					
	Partial replacement of worn floor finishes to offices, common and public areas	1		1.00		Coverings require replacement to prevent accidents and maintain standards
	Partial redecoration of offices, common and public areas	5		6.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
	Redecoration of staircases	5		7.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
Condo	Building & Rear Extension (Internal)					

ltem	Future items for consideration in years ,	Status	Capital	Revenue	£000	Remarks
Ref	2015/16, 2016/17 & 2017/18	* = Energy	Fund (GF)			
		Saving	£000			
18/011	Partial replacement of suspended ceilings	1		10.00		Existing ceiling tiles and support grids are beyond reasonable
						economic repair
	Partial replacement of worn floors	1		3.75		Coverings require replacement to prevent accidents and maintain standards
	Partial redecoration of offices - Conder	5		4.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
	Building & Rear Extension (External)					
	General roof overhaul, leadwork repairs, clearance of valleys and gutters including safe access for working at height	2		5.00		Work required due to deteriation of materials, leading to potential water ingress.
	eld House, Garage & Stores (External)					
18/015	External redecoration of timberwork/windows/doors to house/steel fire escape stairs and provision of anti slip finish to treads.	5		4.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
Bin sto						
	External redecoration of timber and metalwork.	5		0.75		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
			106.00	45.50		
	Il Street Offices (External)	0		0.75		Diele of blooks as if a strug doutelear
	Drainage jetting	2		0.75		Risk of blockage if not undertaken
	Overhaul/repair zinc wall cladding	2		1.00		Cladding requires overhauling to prevent water ingress which would cause damage to the building fabric
	I Street Offices (Internal)					
18/019	Partial internal redecoration of offices and common areas	5		3.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
18/020	Partial replacement of worn floor finishes to offices and common areas	1		2.25		Coverings require replacement to prevent accidents and maintain standards
			0.00	7.00		
00 -						
	Broadway Offices, Loughton	4			4.05	
18/021	Partial replacement of worn floor finishes to offices and common areas	1			4.25	Coverings require replacement to prevent accidents and maintain standards
			0.00	0.00	4.25	
Energine	Denet Enning					
⊏pping	Depot, Epping					

ltem	Future items for consideration in years ,	Status	Capital	Revenue	£000	Remarks
Ref	2015/16, 2016/17 & 2017/18	* = Energy	Fund (GF)			
		Saving	£000			
18/022	Basic standard of repair - Health & Safety				6.50	Work required to comply with Health & Safety and Statutory
10/022	requirements				0.00	Legislation
			0.00	0.00	6.50	
				0.00	0.00	
Langst	on Road Depot, Loughton (External)					
	Depot environmental maintenance	1		0.50		General clearance of weeds, debris and litter. Controls vermin
18/024	Basic standard of repair - Health & Safety requirements	1		3.75		Work required to comply with Health & Safety and Statutory Legislation
18/025	Redecoration/Protection of bollards and RSJs	5		0.50		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
18/026	Redecoration of external doors, including minor repairs	5		2.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
18/027	Isolated areas of repointing and repairs to boundary walls and renewal of movement joints	5		1.50		Repairs to walls are required to minimise deterioration
Langst	on Road Depot (Internal)					
18/028	Partial redecoration of internal common areas	5		5.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
18/029	Clean and change lights in store areas	1		1.00		Health & Safety - Failing light fittings and general dirty condition requires a bulk clean and change
			0.00	14.25		
-						
	ead Depot (External)					
18/030	Environmental maintenance	1		1.20		General clearance of weeds, debris and litter. Controls vermin
18/031	Watercourse maintenance (addition to programme)	1		2.50		Health & Safety - Watercourse requires clearing annually to prevent flooding and control vermin
18/032	Basic standard of repair - Health & Safety requirements	1		3.00		Work required to comply with Health & Safety and Statutory Legislation
			0.00	6.70		
	Veald Airfield, North Weald					
	g 240 - Fire Station (Internal)			0.00		Departed and the regular maintenance to minimize
18/033	Internal redecoration of toilet and lobby areas	5		0.80		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
Gymna	stics Centre (structure, external and roof only)					

ltem Ref	Future items for consideration in years Status Capital Revenue £000 2015/16, 2016/17 & 2017/18 * - Energy Fund (GF)		Remarks						
Rei	2013/10, 2010/17 & 2017/18	* = Energy Saving	£000						
	Maintenance of fire escape routes including clearance of vegetation	1		0.30		Health & Safety requirement			
	to Hangar 1								
18/035	Overhaul roof	1		5.00		Health & Safety - Previously encapsulated asbestos cement roof tiles require upkeep to maintain the integrity of the roof covering and prevent rook leaks (includes for safe working at height			
18/036	Clear and renew damaged rainwater goods	2		1.00		Gutters and downpipes need to be freeflowing and in good order to prevent water ingress into the building (includes for safe working at height)			
			0.00	7.10					
Nurser	/, Pyrles Lane, Loughton								
18/037	Isolated replacement works to water system pipework	2		3.00		Maintains continued provision of water systems			
	Basic standard of repair - Health & Safety requirements	1		3.00		Work required to comply with Health & Safety and Statutory Legislation			
			0.00	6.00					
	n, Waltham Abbey								
Externa									
	External redecoration of rear elevations and extension and redecoration of spiral steel fire escape stairs and provision of anti slip finish to treads and landing	5		5.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards			
Interna									
	Maintenance of boiler	2		0.50		Ensures continued service, efficiency and fuel economy			
	Partial replacement of worn floor finishes to offices and public areas	1		2.00		Coverings require replacement to prevent accidents and maintain standards			
18/042	Partial redecoration of offices and public areas	5		3.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards			
			0.00	10.50					
Public	Foilets, High Street, Ongar								
	Jet through foul water drainage system	2		0.15		Risk of blockage if not undertaken			
18/044	Prepare and redecorate all timber and metalwork surfaces	5		1.50		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards			

ltem	Future items for consideration in years ,	Status	Capital	Revenue	£000	Remarks
Ref	2015/16, 2016/17 & 2017/18	* = Energy Saving	Fund (GF) £000			
18/045	Prepare and redecorate ceilings	5		1.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
			0.00	2.65		
Industr	ial Estates					
	r Road Industrial Estate, Waltham Abbey					
	Environmental maintenance	1		2.80		General clearance of weeds, debris and litter. Controls vermin
	Watercourse maintenance.	1		1.50		Health & Safety - Watercourse requires clearing annually to prevent flooding and control vermin
	od Hill Industrial Estate Workshop Units, Loughton					
18/048	Environmental maintenance	1		1.50		General clearance of weeds, debris and litter. Controls vermin
18/049	Clearance of drainage gullies / channels and joint sealing	2		1.00		Risk of blockage if not undertaken
18/050	Redecoration of timberwork and metal walkway	5		4.50		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
			0.00	11.30		
Enning	Sports Centre, Epping (external & structural)					
	Drainage jetting	2		0.75		Risk of blockage if not undertaken
	Redecoration of fire escape stairs and provision of anti slip finish	5		1.50		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
18/053	Replace any timber doors / windows / cladding etc	2		3.00		Aging fixtures require periodic replacement due to decay and reaching the end of their design lifespan
18/054	Overhaul/repair zinc wall cladding	2		1.75		Cladding requires overhauling to prevent water ingress which would cause damage to the building fabric
			0.00	7.00		~ ~ ~ ~
Lought	on Leisure Centre, Loughton (external & structural)			├		
	Overhaul roof upstands, flashings, details and fixings	2		4.00		Periodic maintenance is required in these areas to prevent water
10/000	overnaui roor upstanus, nashings, detalis and fixings	Z		4.00		ingress damaging the building fabric
18/056	External decorative preservative treatment to exposed sections of glulam beams	5		5.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
18/057	Drainage jetting	2		0.75		Risk of blockage if not undertaken

ltem	Future items for consideration in years ,	Status	Capital	Revenue	£000	Remarks
Ref	2015/16, 2016/17 & 2017/18	* = Energy	Fund (GF) £000			
19/059	Redecorate railings to yard/access road	Saving		1.20		Decoration requires regular maintenance to minimise
10/000	Redecorate rainings to yard/access road	5		1.20		deterioration through wear and tear and to maintain visual
						standards
18/059	Redecorate steel columns, beams and tie bars above	5		2.80		Decoration requires regular maintenance to minimise
	main entrance	5		2.00		deterioration through wear and tear and to maintain visual
						standards
			0.00	13.75		
	eisure Centre, Ongar (external & structural)					
18/060		1		0.50		Health & Safety - To maintain a level of security and public
	Isolated lamp replacements to car park street lighting					safety
	Clear all gullies and jet through surface water drains to	2		1.75		Risk of blockage if not undertaken
	yards, car parks and walkways including emptying					
	petrol interceptors and cleaning filters					
			0.00	2.25		
NA (- 141						
	m Abbey Swimming Pool, Waltham Abbey (external a			0.50		
18/062		5		0.50		Decoration requires regular maintenance to minimise
	External redecoration of entrance wall					deterioration through wear and tear and to maintain visual standards
	Drainage jetting	2		0.75		Risk of blockage if not undertaken
	Preservative treatment to fences and gates	5		2.75		Decoration requires regular maintenance to minimise
10/004	These value treatment to rences and gates	5		2.75		deterioration through wear and tear and to maintain visual
						standards
			0.00	4.00		
	Owned Shopping Parades					
	s Lane, Loughton (58 to 76)					
	Drainage Jetting	2		0.75		Risk of blockage if not undertaken
18/066	Environmental maintenance	1		0.80		General clearance of weeds, debris and litter. Controls vermin
18/067	External redecoration of extensions and exposed low	5		2.50		Decoration requires regular maintenance to minimise
	level timber and metalwork to rear of parade	-				deterioration through wear and tear and to maintain visual
	•					standards
18/068	Clean and change lamps to wall mounted fittings	1		0.50		Health & Safety - To maintain a level of security and public
						safety
	se, Waltham Abbey (1 to 12)					
	Clear all gullies and jet through surface water drains to	2		0.50		Risk of blockage if not undertaken
	yards, car park and walkways					
Limes A	Avenue, Chigwell (548 to 562 including covered walk	way and com	mon areas)			

ltem	Future items for consideration in years ,	Status	Capital	Revenue	£000	Remarks
Ref	2015/16, 2016/17 & 2017/18	[*] = Energy Saving	Fund (GF) £000	£000		
18/070	Pressure washing and general maintenance of undercover paved areas and environmental maintenance to yard car park and walkways	1		2.50		Health & Hygiene - removal of chewing gum, litter, weeds, urine etc.
18/071	Clear all gullies and jet through foul and surface water drains to yard, car park and undercover walkway	2		0.75		Risk of blockage if not undertaken
18/072	Re-line mark faded parking bays and symbols to car park	5		0.50		Line markings are fading and require attention to ensure parking is controlled
18/073	Redecoration of walls, ceilings gates and railings to undercover walkway	5		2.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
18/074	Clean and change lamps under canopy	1		0.50		Health & Safety - To maintain a level of security and public safety
	Carry out repairs to flat roof including fasciae, soffits and edge trims	2		3.00		Work required due to deteriation of materials, leading to potential water ingress.
	on Way, Buckhurst Hill (142 to 164)					
18/076	Environmental maintenance	1		0.40		General clearance of weeds, debris and litter. Controls vermin
18/077	Preservative treatment to fences and gates	5		2.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
Lower	Queens Road, Buckhurst Hill (1, 4, 5 & 8)					
18/078	Redecoration of walls, ceilings and metalwork to undercover walkway and railings to side of parade	5		0.80		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
	Square, Waltham Abbey (15 to 19)					
	Clear all gullies and jet through surface water and foul drains to yard and paved areas	2		0.40		Risk of blockage if not undertaken
Parklar	nds Coopersale (28 to 31)					
18/080	Clear all gullies and jet through surface water drains to yard and paved areas	2		0.25		Risk of blockage if not undertaken
18/081	Environmental maintenance	1		0.30		General clearance of weeds, debris and litter. Controls vermin
Pyrles	Lane, Loughton (34 to 52)		1			
	Preservative treatment to fences and gates and redecoration of garage doors	5		3.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
Round	hills, Waltham Abbey (74 to 82)					
	Re-line mark faded parking bays and symbols to car park	5		0.50		Line markings are fading and require attention to ensure parking is controlled

ltem	Future items for consideration in years ,	Status	Capital	Revenue	£000	Remarks
Ref	2015/16, 2016/17 & 2017/18	* = Energy Saving	Fund (GF) £000			
	Clean and change lamps under canopy, end floodlight and yard lighting	1		0.60		Health & Safety - To maintain a level of security and public safety
	oadway, Loughton (11 to 73 & 12 to 82)					
18/085	Environmental Maintenance	1		2.25		General clearance of weeds, debris and litter. Controls vermin
Upshire	e Road, Waltham Abbey (113 to 123)					
	Preservative treatment to fences and gates	5		1.00		Decoration requires regular maintenance to minimise deterioration through wear and tear and to maintain visual standards
			0.00	25.80		
Genera	I Improvement Areas					
	Road, Buckhurst Hill					
	Environmental maintenance	1		1.50		General clearance of weeds, debris and litter. Controls vermin
18/088	Clear all gullies and jet through surface water drains to road areas	2		0.50		Risk of blockage if not undertaken
Woolla	rd Street, Waltham Abbey					
	Environmental maintenance	1		0.50		General clearance of weeds, debris and litter. Controls vermin
			0.00	2.50		
Health	& Safety Works					
	Public building electrical testing, fire precaution requirements, fire fighting equipment servicing, asbestos management, water treatment works, amendments to statutory regulations	1		8.00		Work required to comply with Health & Safety and Statutory Legislation
			0.00	8.00		
Contin						
Conting CP101	Capital Contingency	1	25.00			To cover status 5 and unexpected works on the Capital
18/091	Emergency Repairs	1		5.00		programme To cover unexpected works on the Revenue programme
		-	25.00	5.00		
	Funding for the year 2017/18		131.00	179.30	10.75	
	Total Revenue		131.00	179.30	190.05	
	Current DDF Approved Budget			L	0.00	
	Grand Total (Revenue)				190.05	
	Less CSB allocated				118.00	

ltem Def	Future items for consideration in years ,	Status	Capital	Revenue	£000	Remarks
Ref	2015/16, 2016/17 & 2017/18	* = Energy	Fund (GF) £000			
		Saving	2000		-	
	Less HRA allocated				6.50	
	Net DDF requirement for 2017/18				65.55	
	Capital schemes - additional funding		0.00			
	Capital finance schemes previously approved		0.00			
	Net funding required		131.00			
	Total Capital expenditure		131.00			

Project Ref	Items	2013/14 Forecast £000	2014/15 Forecast £000	2015/16 Forecast £000	2016/17 Forecast £000	2017/18 Forecast £000	5 Year Total £000
	Civic Offices, High Street, CM16 4BZ						
0.0.4	Electrical/Mechanical						
	Energy Saving Grant	20					20
	Part DDA Compliance. Part resolution of Security problems. Provision of automatic opening doors. C/F 2011/12	59					59
CP008	Photovoltaic Panel on the Main Building, Condor Building and Rear Extension, including pre work protection.	20	180				200
CP111	Replacement of failing lighting fittings in offices in the Conder building.	29	20	20	20	20	109
	Replacement of lighting in offices in the Civic Building inc 323 House with LED lighting	20	20		20	20	100
	Electrical load management	32	11	11			54
	New generator				55		55
	Fire Alarm – Replacement Smoke and Heat Detection Loop 2	11					11
	Fire Alarm – Replacement Smoke and Heat Detection Loop 4 and 5		11				11
	Fire Alarm – Replacement Smoke and Heat Detection Loop 3			5			5
	Fire Alarm – New Loops and Cards		16				16
	Fire Alarm – New Smoke and Heat Detection			16	16		32
18/001	Fire Alarm System - Major Upgrade of System Control and Amplifiers					10	10
	Fire Alarm System - Speaker Replacement					10	10
	Energy Conservation - Provision of Power Factor Correction to increase the efficiency of electricity use	11					11
CP136	Energy Conservation - Provision of Voltage Regulation Equipment to reduce energy consumption and electricity charges; intake revision and provision of Air Circuit Breaker	11					11
CP137	Electric, Gas and Main MWS Smart Metering	16	15	10			41
	North toilet Fresh Air supply & Extract air handling units replacement	15					15
	Ceiling replacement to Conder 2nd floor corridor including cable management and new Lighting plus Condor staircase	27					27
CP134	Upgrade Civic Building sensor points and Trend outstation to unify heating control throughout the Main Building	10					10
CP129	Plant Room 6 - Replacement AC compressor unit	16					16
	Plant Room 3 - Replacement AC compressor unit	10	20				20
	Condor Lift Motor Room - Install AC unit	5					5
	Trend - Interface upgrade	ľ	11				11
	Daikin - Interface upgrade		10				10
	Boiler House replacement pumps	1	28				28
	Tower Toilet Fresh Air supply & Extract air handling units replacement			14			14

Project Ref	Items	2013/14 Forecast £000	2014/15 Forecast £000	2015/16 Forecast £000	2016/17 Forecast £000	2017/18 Forecast £000	5 Year Total £000
17/003	Plant Room 3 - Replacement supply/extract fans to Member Suite				30		30
16/004	Plant Room 2 - Replacement supply/extract fans to Council Chamber			40			40
18/003	Plant Room 2 - Replacement supply/extract fans to internal office space					12	12
18/004	Plant Room 3 - Replacement supply/extract fans to Staff Recreation area					12	12
16/005	Homefield House - Upgrades to power lighting and fire alarms			22			22
17/004	Computer Suite 2 - Replacement AC units				55		55
17/005	Cash Suite - Air handling Unit				90		90
18/005	Replacement of Major Pumps to Boiler House.					12	12
16/006	Phased replacement of Electrical Power Distribution Boards / MCB's MCBO's due to life extinction.			10	10	10	30
	Main Building (Internal)						
CP153	Refurbish 1st floor north Toilets			37			
CP154	Refurbish ground floor north toilets, including accessible toilet			51			
17/058	Refurbish Tower first floor toilets, including accessible toilets				46		46
17/059	Refurbish Tower ground floor toilets, including accessible toilets				49		49
CP127	Widen doors to Housing interview room and Conference Room to facilitate DDA	16					16
	Main Building (External)						
	Roof Access	6					6
CP155	Remodel outside front seating area and hard landscaping and replace front entrance doors and porch to facilitate DDA		15				15
CP156	Replacement if the concrete seating at the front of the building, with 2 tier brick planters.		20				20
CP157	1 of 2 Replacement of the windows in the Main Building, North and West facing.		135				135
	2 of 2 Replacement of the windows in the Main Building, East facing and link bridge.			160			160
CP158	Reline lead valley around council chamber where split and defective and water is now seeping through to the roof deck below. Repair and overcoat numerous splits, cracks, holes and the like to roof sheets, valley gutters, flashings, joints and details		15				15
	Conder Building & Rear Extension (Internal)						
CP104	Refurbishment of ground floor ladies and first floor gents toilets	14					14
CP107	Partial replacement of suspended ceilings	1					1
	Conder Building & Rear Extension (External)						
CP126	Traffic calming - Speed hump and zebra crossing	10					10
CP138	Fire escape staircase remodelled including new handrails to rear internal staircase	12					12
	Replacement of degraded felt in gutters, soffits/fascias. Clear out gutters and replace slipped slates. Including for scaffolding/safe access for working at height.		25				25

Project Ref	Items	2013/14 Forecast £000	2014/15 Forecast £000	2015/16 Forecast £000	2016/17 Forecast £000	2017/18 Forecast £000	5 Year Total £000
	323 House (External)						
CP131	Replacement of decaying and leaking rainwater goods, degraded felt in gutters, overall	12					12
	soffits/fascias. Including for scaffolding/safe access for working at height.						
	63 The Broadway Office						
CP139	Replacement of obsolete suspended ceiling and associated light fittings	11					11
	North Weald Airfield						
	Control Tower (External)						
CP105	Prepare existing flat roof surfaces and apply waterproof coating	6					6
CP140	Upgrade antiquated vertical means of escape ladders to comply with current H&S standards	8					8
	Building 240 - Fire Station (External)						
CP144	Overlay existing felted roof, include for safe access for working at height.	10					10
	Oakwood Hill Industrial Estate Workshop Units						
	Upgrade Industrial Units	13	300				313
16/038	Electro-hydraulic lift installation			77			77
	Epping Sports Centre, Epping (external & structural)						
CP141	Resurface car park including reline marking		13				13
	Waltham Abbey Swimming Pool, Waltham Abbey (external & structural)						
CP159	Resurface car park and access road including re line marking		37				37
CP011	Repairs to Flat Roof	10					10
	Limes Centre (Internal)						
CP145	Install a Building Management System to control the heating and ventilation	10					10
CP160	Install a new access to the plant room to avoid going through doctors consulting room, cost to divert statutory services.		25				25
CP161	Acoustic reduction in both halls		10				10
	Council Owned Shopping Parades						
	Borders Lane, Loughton (58 to 76)						

Project Ref	Items	2013/14 Forecast £000	2014/15 Forecast £000	2015/16 Forecast £000	2016/17 Forecast £000	2017/18 Forecast £000	5 Year Total £000
	Hillhouse, Waltham Abbey (1 to 12)						
CP124	Overlay cracked asphalt roofs covering to rear extensions	7					7
	Limes Avenue, Chigwell (548 to 562)						
17/043	Resurface rear yard				10		10
	Roundhills, Waltham Abbey						
17/050	Mineral cap sheet overlay to front canopy felt roof				6		6
	Upshire Road, Waltham Abbey (113 to 123)						
CP118	Shops Environmental Improvement				65		65
	Chigwell Row Recreation Ground						
CP142	Replacement of failed and damaged concrete path adjacent court area including provision of access route for contractors vehicles	17					17
CP143	Renewal of bitumen seals between concrete bays to footpaths and car park, including minor concrete repairs	10					10
CP101	Capital Contingency	36	25	25	25	25	136
	Grand Total	511	962	518	497	131	2530
	Approved Planned Maintenance Budget Oct 2012	367	431	332	298	0	1428
	Other Approvals and Carried Forward from Previous Year	547	188	0	0	0	735
	Budget Approved todate	914	619	332	298	0	2163
	Recommended Reprofiling	-403	338	0	65	0	0
	New Bid	0	5	186	134	131	456
	Proposed Budget	511	962	518	497	131	2619

Ар	pend	ix 5
----	------	------

Facilities Management 5 Year Revenue Programme

Project		2013/14	2014/15	2015/16	2016/17	2017/18	5 Year
Ref	Items	Forecast £000	Forecast £000	Forecast £000	Forecast £000	Forecast £000	Total £000
			~~~~	~~~~	~~~~	~~~~	
	Civic Offices, High Street, CM16 4BZ						
	Electrical/Mechanical						
DF222	Statutory Portable Electrical Testing of electrical appliances	17.20		11.00			28.20
DF212	Statutory Testing of Electrical Installation & rectification of defects	39.60			20.00		59.60
DF224	Energy Efficiency Work	19.50					
DF209	Emergency Lighting Replacement & Battery Replacements	5.00	5.00	5.00	5.00		20.00
17/007	UPS maintenance and battery replacement				2.50		2.50
DF211	Auto change over on main domestic hot water pumps	2.00					2.00
DF207	Mechanical and electrical upgrade to service area above Council Chamber	3.00					3.00
DF213	Replace boiler house door to comply with Gas Safe regs	2.00					2.00
	Main Building (External)						
14/001	Brickwork and hopper repairs to parapet walls including access lorry boom and operator for		8.00				8.00
	safe working at height						
17/008	Redecoration of general metalwork surfaces, railings, handrails, gates and staircases				5.00		5.00
16/010	Specialist cleaning of stonework and rendered façades			10.00			10.00
16/008	Jet through all foul and surface water drains			4.50			4.50
14/002	Redecoration of general timber surfaces	4.00		4.00		4.00	12.00
14/003	Reseal joints to parapet wall coping stones		6.00				6.00
14/004	High level decoration to steelwork - North and South elevations inc for scaffolding for safe working at height		7.00				7.00
DF210	Reseal / remastic 2nd floor windows, inc for scaffolding for safe working at height		49.00				49.00
	Main Building (Internal)						
14/005	Partial replacement of worn floor finishes to offices, common and public areas	1.00	1.00	1.00	1.00	1.00	5.00
14/006	Partial redecoration of offices, common and public areas	9.00	6.00	6.00	6.00		33.00
	Redecoration of staircases	3.50				7.00	10.50
14/008	Renew 1st floor carpets	4.00					4.00
14/009	Redecorate Committee Rooms 1+2	1.50		1.50			3.00
	Renew floor mats to all entrances		1.65				1.65
	Renew and repair window blinds			4.00			4.00
	Repaint/decorate recreation room			1.25			1.25
	Refurbish 1st floor kitchen		6.00				6.00
	323 House (External)						
14/010	Redecoration of windows and doors	2.60					2.60

	Facilities Management 5 Year Revenu		amme			At	ppendix 5
4/011	Asphalt roof repairs and flashing on Bay roof to South elevation of Link inc safe working at height	3.00					3.00
	Conder Building & Rear Extension (Internal)						
4/012	Partial replacement of worn floors	4.50	3.75	3.75	3.75	3.75	19.50
4/013	Partial redecoration of offices - Conder	5.00	4.00	4.00	4.00	4.00	21.00
14/014	Redecoration of rear staircase	1.70					1.70
14/015	Partial replacement of worn floor finishes to offices and common areas - Rear Extension	4.00					4.00
14/016	Partial internal redecoration of offices and common areas	3.00	3.00				6.00
14/097	Partial replacement of suspended ceilings		10.00	10.00	10.00	10.00	40.00
	Conder Building & Rear Extension (External)						
18/014	General roof overhaul, leadwork repairs, clearance of valleys and gutters including safe access for working at height					5.00	5.00
15/010	Redecoration and timber treatment		4.25				4.25
	Homefield House, Garage & Stores (External)						
18/015	External redecoration of timberwork/windows/doors to house/steel fire escape stairs and					4.00	4.00
	provision of anti slip finish to treads.						
	Bin store						
18/016	External redecoration of timber and metalwork.					0.75	0.75
	Pyramid Building						
14/017	External & internal redecoration	1.25					1.25
	Hemnall Street Offices (External)						
16/022	Redecoration to main building			10.00			10.00
14/018	Drainage jetting	0.75	0.75	0.75	0.75	0.75	3.75
14/019	External redecoration to single storey section of building including timber windows, doors and glazed walls at ground floor level including minor repairs and redecorate metal railings, handrails and bollards	7.00			7.00		14.00
14/020	Overhaul/repair zinc wall cladding	1.00				1.00	2.00
15/011	Repoint side elevation of chimney stack facing sports centre including access tower for safe working at height		1.50				1.50
	Hemnall Street Offices (Internal)						
14/021	Partial internal redecoration of offices and common areas	3.00				3.00	6.00
	Partial replacement of worn floor finishes to offices and common areas	2.25				2.25	4.50
<u> </u>							
	63 The Broadway Offices, Loughton						
14/023	Partial replacement of worn floor finishes to offices and common areas	4.25				4.25	8.50
14/024	Partial internal redecoration of offices and common areas	3.50					3.50

		D				A	ppendix 5
	Facilities Management 5 Year Reven	ue Progr	amme				
	Epping Depot, Epping						·
14/034	Basic standard of repair - Health & Safety requirements	6.50	6.50	6.50	6.50	6.50	32.50
14/035	Renewal of gates to lower yard	2.00					2.00
	Langston Road Depot, Loughton (External)						
14/029	Depot environmental maintenance	0.50	0.50	0.50	0.50	0.50	2.50
14/028	Basic standard of repair - Health & Safety requirements	3.75	3.75	3.75	3.75	3.75	18.75
14/030	Redecoration/Protection of bollards and RSJs	0.50				0.50	1.00
14/031	Redecoration of external doors, including minor repairs	2.00				2.00	4.00
18/027	Isolated areas of repointing and repairs to boundary walls and renewal of movement joints					1.50	1.50
14/032	Redecoration of external fire escape stairs and provision of anti slip finish	2.80					2.80
	Langston Road Depot (Internal)						
14/033	Partial redecoration of internal common areas	5.00				5.00	10.00
18/029	Clean and change lights in store areas					1.00	1.00
	Townmead Depot (External)						
14/037	Environmental maintenance	1.20	1.20	1.20	1.20	1.20	6.00
14/038	Watercourse maintenance	2.50	2.50	2.50	2.50	2.50	12.50
14/036	Basic standard of repair - Health & Safety requirements	3.00	3.00	3.00	3.00	3.00	15.00
15/019	Redecorate including minor repairs		5.50				5.50
	North Weald Airfield, North Weald						
	Gatehouse (External)						
14/058	External redecoration and timber treatment	2.25					2.25
	Gatehouse (Internal)						
14/059	Internal redecoration of offices and common areas	3.50					3.50
14/060	Overhaul ceiling	1.50					1.50
	Control Tower (External)						
14/062	External redecoration to concrete, masonry and metalwork including safe access for working	5.00					5.00
	at height						
14/061	Replace areas of broken glass	6.03					
4 5 / 6 6 6	Control Tower (Internal)						
15/020	Partial internal redecoration of offices		4.00				4.00
4 = 10 = 1	Building 240 - Fire Station (External)						
15/021	Clean and change lights		0.75				0.75
	Building 240 - Fire Station (Internal)						
14/067	Internal redecoration of toilet and lobby areas	0.80				0.80	1.60
	Archive Store (External)						

#### Facilities Management 5 Year Revenue Programme

Appendix 5

14/065 Repointing to external walls 1.00 1.00 2.75 14/066 Preservative treatment and redecoration to external timber fascias, soffits, doors and panels 2.75 5.50 Gymnastics Centre (structure, external and roof only) 14/063 Maintenance of fire escape routes including clearance of vegetation 0.30 0.30 0.30 0.30 0.30 1.50 Clear all gullies and drainage channels to car park areas and jet through surface water 0.25 15/023 0.25 0.50 drainage Preservative treatment to timber oil storage tank enclosure 14/064 0.60 0.60 1.20 Annexe to Hangar 1 18/035 Overhaul roof 5.00 5.00 18/036 Clear and renew damaged rainwater goods 1 00 1 00 Nursery, Pyrles Lane, Loughton 18/037 Isolated replacement works to water system pipework 3.00 3.00 Basic standard of repair - Health & Safety requirements 3.00 14/051 3.00 3.00 3.00 3.00 15.00 Museum, Waltham Abbey External External redecoration of rear elevations and extension and redecoration of spiral steel fire 18/039 5.00 5.00 escape stairs and provision of anti slip finish to treads and landing 5.00 Redecorate front/side elevations 15/025 5.00 Internal 14/053 Maintenance of boiler 0.50 0.50 0.50 0.50 0.50 2.50 16/032 Partial replacement of worn floor finishes to offices and public areas 2.00 2.00 4.00 14/055 Sand and reseal timber flooring to public areas 0.00 16/033 Partial redecoration of offices and public areas 6.00 3.00 3.00 Improvements to lighting installations and controls (see Museum Manager) 14/057 0.00 Limes Farm Multi-Use Games Area, Chigwell Clean and change lamps to floodlights including safe access for working at height 14/053 1.25 1.25 Public Toilets, High Street, Ongar 14/068 Jet through foul water drainage system 0.15 0.15 0.15 0.15 0.15 0.75 Prepare and redecorate all timber and metalwork surfaces 14/069 1.50 1.50 3.00 2.00 Prepare and redecorate ceilings 1.00 14/070 1.00 Remove failing electric security releases (automatically lock doors 'out of hours') to entrance 15/028 1.50 1.50 **Industrial Estates Brooker Road Industrial Estate, Waltham Abbey** 

	Facilities Management 5 Year Reve	nue Progra	mme			Αι	opendix 5
14/025	Environmental maintenance	2.80	2.80	2.80	2.80	2.80	14.00
15/030	Watercourse maintenance (addition to programme)	2.00	1.50	1.50	1.50	1.50	6.00
14/026	Patch repair and white line lower end car park	4.75	4.75	1.50	1.50	1.50	9.50
14/020	Oakwood Hill Industrial Estate Workshop Units, Loughton	4.75	4.75				0.00
14/027	Environmental maintenance	1.50	1.50	1.50	1.50	1.50	7.50
15/034	Clearance of drainage gullies / channels and joint sealing		1.00			1.00	2.00
15/033	Redecoration of timberwork and metal walkway		4.50			4.50	9.00
	Sports Centres						
15/075	Detailed condition survey of the 4 Leisure Facilities		49.20				49.20
	Epping Sports Centre, Epping (external & structural)						
14/046	Drainage jetting	0.75	0.75	0.75	0.75	0.75	3.75
16/040	Decorations including minor repairs			2.50			2.50
18/052	Redecoration of fire escape stairs and provision of anti slip finish					1.50	1.50
18/053	Replace any timber doors/ windows / cladding etc?					3.00	3.00
14/047	Overhaul/repair zinc wall cladding	1.75				1.75	3.50
	Loughton Leisure Centre, Loughton (external & structural)						
14/039	Overhaul roof upstands, flashings, details and fixings	4.00		4.00		4.00	12.00
15/039	External decorative preservative treatment to exposed sections of glulam beams		5.00			5.00	10.00
14/045	Drainage jetting	0.75	0.75	0.75	0.75	0.75	3.75
14/041	Fire damper repairs	7.00					
15/041	Clean and restore stained blockwork and reconstituted stone including safe access for working at height		7.00				7.00
15/037	Redecorate railings to yard/access road		1.20			1.20	2.40
15/038	Redecorate steel columns, beams and tie bars above main entrance		2.80			2.80	5.60
15/040	Renew perished movement joints to wall and around penetrations into building		5.25				5.25
16/043	Apply preservative treatment to windows and doors of Octagon building			1.00			1.00
	Ongar Leisure Centre, Ongar (external & structural)						
16/045	Isolated lamp replacements to car park street lighting			0.50		0.50	1.00
14/048	Clear all gullies and jet through surface water drains to yards, car parks and walkways	1.75	1.75	1.75	1.75	1.75	8.75
15/044	Patching/Repairs of roof copings, Movement and Joints		4.50		4.50		9.00
14/049	Service and clean streetlights and replace lamps	1.50			1.50		3.00
14/050	Apply preservative treatment to windows, doors and cladding	3.75		1	3.75		7.50
15/043	Lamp replacements to street lights		0.50				0.50

# Facilities Management 5 Year Revenue Programme

Appendix 5

15/045	Reline markings to car park		4.25				4.25
	Waltham Abbey Swimming Pool, Waltham Abbey (external & structural)						
14/044	External redecoration of entrance wall	0.50	0.50	0.50	0.50	0.50	2.50
14/045	Drainage jetting	0.75	0.75	0.75	0.75	0.75	3.75
14/042	Upgrading of footpath from rear fire exits	3.00					3.00
14/043	Preservative treatment to fences and gates	2.75				2.75	5.50
15/048	Redecorate previously decorated surfaces, fascias, soffits, timber and metalwork		5.75				5.75
	Limes Centre (Internal)						
15/049	Knock through wall between 2 halls storage cupboards		2.50				2.50
	Council Owned Shopping Parades						
	Borders Lane, Loughton (58 to 76)						
14/072	Drainage Jetting	0.75	0.75	0.75	0.75	0.75	3.75
14/073	Environmental maintenance	0.80	0.80	0.80	0.80	0.80	4.00
14/071	Partial repoint of brick wall enclosing rear yards including minor repairs as necessary	4.00					4.00
14/074	External redecoration of extensions and exposed low level timber and metalwork to rear of	2.50		2.50		2.50	7.50
15/052	Clean and change lamps to wall mounted fittings		0.50			0.50	1.00
	Hillhouse, Waltham Abbey (1 to 12)						
14/075	Clear all gullies and jet through surface water drains to yards, car park and walkways	0.50	0.50	0.50	0.50	0.50	2.50
	Limes Avenue, Chigwell (548 to 562 including covered walkway and common areas)						
14/076	Pressure washing and general maintenance of undercover paved areas and environmental	2.50	2.50	2.50	2.50	2.50	12.50
14/077	Clear all gullies and jet through foul and surface water drains to yard, car park and	0.75	0.75	0.75	0.75	0.75	3.75
18/072	Re-line mark faded parking bays and symbols to car park					0.50	0.50
14/078	Redecoration of walls, ceilings gates and railings to undercover walkway	2.00		2.00		2.00	6.00
14/079	Clean and change lamps under canopy	0.50				0.50	1.00
15/056	Carry out repairs to flat roof including fascias, soffits and edge trims		3.00			3.00	6.00
	Loughton Way, Buckhurst Hill (142 to 164)						
14/080	Environmental maintenance	0.40	0.40	0.40	0.40	0.40	2.00
15/058	Preservative treatment to fences and gates		2.00			2.00	4.00
	Lower Queens Road, Buckhurst Hill (1, 4, 5 & 8)						
14/081	Redecoration of walls, ceilings and metalwork to undercover walkway and railings to side of parade	0.80		0.80		0.80	2.40
15/059	Clean and change lamps to wall and ceiling mounted light fittings		0.50				0.50
	Market Square, Waltham Abbey (15 to 19)						

	Facilities Management 5 Year Reven	ue Progra	imme			Αι	opendix 5
14/082	Clear all gullies and jet through surface water and foul drains to yard and paved areas	0.40	0.40	0.40	0.40	0.40	2.00
14/082	Clean and change lamps under canopy	1.75	0.40	0.40	0.40	0.40	1.75
14/000		1.75					1.75
	Parklands Coopersale (28 to 31)						
14/084	Clear all gullies and jet through surface water drains to yard and paved areas	0.25	0.25	0.25	0.25	0.25	1.25
14/085	Environmental maintenance	0.30	0.30	0.30	0.30	0.30	1.50
15/064	Clean and change lamps under canopy and to floodlights	0.00	0.40	0.00	0.00	0.00	0.40
16/060	Redecoration of front canopy and common areas		0110	4.75			4.75
	Pyrles Lane, Loughton (34 to 52)						
14/086	Preservative treatment to fences and gates and redecoration of garage doors	3.00				3.00	6.00
14/096	Overlay cracked asphalt roof to rear extensions		4.40				4.40
	Roundhills, Waltham Abbey (74 to 82)						
18/083	Re-line mark faded parking bays and symbols to car park					0.50	0.50
14/087	Clean and change lamps under canopy, end floodlight and yard lighting	0.60				0.60	1.20
15/066	Redecoration of front canopy, staircase elevation, bollards and barriers		2.50				2.50
	The Broadway, Loughton (11 to 73 & 12 to 82)						
14/088	Environmental Maintenance	2.25	2.25	2.25	2.25	2.25	11.25
15/067	Upgrade of undercover walkway, balcony fascias and tiled frontage		17.00				
	The Street, High Ongar (48 & 50)						
14/089	Decoration, including minor overhaul of roof and anti-slip coating to stairs	6.25					6.25
	Upshire Road, Waltham Abbey (113 to 123)						
18/086	Preservative treatment to fences and gates					1.00	1.00
	83 Loughton Way, Buckhurst Hill, Dentist Surgery						
14/090	Partial repointing of external walls and external redecoration including safe access for	3.25					
	General Improvement Areas						
	Alfred Road, Buckhurst Hill						
14/091	Environmental maintenance	1.50	1.50	1.50	1.50	1.50	7.50
14/092	Clear all gullies and jet through surface water drains to road areas	0.50	0.50	0.50	0.50	0.50	2.50
15/070	Carry out isolated repairs to close boarded timber fences and apply preservative treatment		5.00	5.00			10.00
	(section to Alfred Rd)						
16/069	Carry out isolated repairs to Private Road and Unregulated Parking Area (section to Alfred			1.00			1.00
	Rd)						
	Woollard Street, Waltham Abbey						
14/093	Environmental maintenance	0.50	0.50	0.50	0.50	0.50	2.50
	Chigwell Row Recreation Ground						
16/066	Renewal of timber kick boards to court areas and replacement of 2 No timber gates and			5.00			5.00

		_					Appendix 5					
	Facilities Management 5 Year Revenue Programme											
	Health & Safety Works											
14/094	Public building electrical testing, fire precaution requirements, fire fighting equipment	8.00	8.00	8.00	8.00	8.00	40.00					
	Contingency Fund											
14/095	Emergency Repairs	5.00	5.00	5.00	5.00	5.00	25.00					
17/057	Consultants report for 5 year programme				20.00							
	Grand Total	305.33	323.50	166.90	154.45	190.05	1140.23					
	Less Existing Planned Maintenance CSB Budget	118.00	118.00	118.00	118.00	118.00	590.00					
	Less Existing Planned Maintenance HRA Budget	16.25	6.50	6.50	6.50	6.50	42.25					
	Current DDF Approved Budget	230.00	39.00	11.00	-23.00	0.00	257.00					
	Increase/(reduction) in requirement	-58.92	160.00	31.40	52.95	65.55	250.98					
	Proposed Budget	305.33	323.50	166.90	154.45	190.05	1140.23					
	Amount not required if New Windows in Main Building installed	0.00	49.00	0.00	0.00	0.00	49.00					
	Amended requirement	-58.92	111.00	31.40	52.95	65.55	201.98					